

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS
47.94

Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 32, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 26 ins. in the ground, with brass cap mkd.

T23SR6W

$\frac{1}{4}$ S 29
S 32

1957

from which

A fir, 18 ins. diam., bears S. 89° E., 83 lks. dist.,
mkd. $\frac{1}{4}$ S32 BT.

A madrone, 13 ins. diam., bears N. 79°30' W., 44 lks. dist.,
mkd. $\frac{1}{4}$ S29 BT.

Descend 327 ft. over W. slope.

56.80 Creek, 3 lks. wide, course S. 10° E.; asc. 424 ft. over E. slope.

65.97 Ridge, bears N. 50° W. and S. 50° E.; desc. 54 ft. over SW. slope.

73.92 Gully, drains S. 45° E.; asc. 132 ft. over E. slope.

77.20 Road, unimproved, 20 lks. wide, bears S. 10° E. and N. 10° W.;
ridge, bears S. 10° E. and N. 10° W.; desc. 337 ft. over SW. slope.

95.88 The cor. of secs. 29, 30, 31, and 32.

Land, mountainous. Soil, sandy loam, rock outcroppings. Timber,
fir, hemlock, and cedar. Undergrowth, salal, poison oak, and
vine maple.

S. 88°58' W., bet. secs. 30 and 31.

Descend 130 ft. over SW. slope.

15.86 Spur, slopes SW.; desc. 130 ft. over SW. slope.

22.79 Road, graded, 25 lks. wide, bears N. 10° W. and S. 10° E.; desc.
135 ft. over SW. slope.

28.47 Bear Creek, 10 lks. wide, course S. 15° E.; asc. 770 ft. over E.
slope, changing to SE. slope.

42.77 Spur, slopes N. 60° E.; asc. 130 ft. over NE. slope.

47.76 Point for the $\frac{1}{4}$ sec. cor. of secs. 30 and 31, at proportionate
distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 26 ins. in the
ground, with brass cap mkd.

T23SR6W

$\frac{1}{4}$ S 30
S 31

1957

from which

A fir, 13 ins. diam., bears N. 26° W., 60 lks. dist.,
mkd. $\frac{1}{4}$ S30 BT.

A fir, 18 ins. diam., bears S., 43 lks. dist.,
mkd. $\frac{1}{4}$ S31 BT.