

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS

T23SR6W
 $\frac{S19}{S30} | \frac{S20}{S29}$
 1957

from which

- A fir, 25 ins. diam., bears N. 16° E., 88 lks. dist., mkd. T23S R6W S20 BT.
- A fir, 28 ins. diam., bears S. 76° E., 24 lks. dist., mkd. T23S R6W S29 BT.
- A fir, 29 ins. diam., bears S. 50½° W., 83 lks. dist., mkd. T23S R6W BT.
- A fir, 33 ins. diam., bears N. 1° W., 4 lks. dist., mkd. T23S R6W S19 BT.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, poison oak, vine maple, salal, and madrone.

From the cor. of secs. 20, 21, 28, and 29.

N. 89°43' W., bet. secs. 20 and 29.

Ascend 134 ft. over E. slope.

- 6.10 Road, unimproved, 15 lks. wide, bears NE. and SW.; desc. 170 ft. over W. slope.
- 12.76 Swale, drains NW.; desc. 92 ft. over NW. slope.
- 20.34 Point for the E 1/16 sec. cor. of secs. 20 and 29.

Set an iron post, 30 ins. long, 2 ins. diam., 10 ins. in the ground to solid rock, and in a mound of stone, 4 ft. base, to top, with brass cap mkd.

T23SR6W
 E 1/16 $\frac{S 20}{S 29}$
 1957

from which

- A fir, 18 ins. diam., bears N. 27½° E., 50 lks. dist., mkd. E 1/16 S20 BT.
- A fir, 20 ins. diam., bears S. 50° E., 20 lks. dist., mkd. E 1/16 S29 BT.

Ascend 315 ft. over E. slope.

- 28.48 Ridge, bears N. and S.; desc. 5 ft. over W. slope.
- 28.78 Road, unimproved, 20 lks. wide, bears NW. and SE.; desc. 124 ft. over SW. slope.
- 40.68 Point for the ¼ sec. cor. of secs. 20 and 29, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T23SR6W
 $\frac{1}{4} \frac{S 20}{S 29}$
 1957

from which