

County Surveyor's Record, Douglas County, Oregon
90

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS

from which

A fir, 14 ins. diam., bears S. $87\frac{1}{2}^\circ$ E., 44 lks. dist.,
mkd. $\frac{1}{4}$ S17 BT.

A fir, 28 ins. diam., bears N. 72° W., 95 lks. dist.,
mkd. $\frac{1}{4}$ S18 BT.

N. $44^\circ 40'$ W., beginning new measurement.

Descend 109 ft. over N. slope.

3.31 Creek, 15 lks. wide, course W.; desc. 516 ft. over SW. slope,
changing to W. slope.

31.35 Creek, 5 lks. wide, course N. 10° W.; asc. 345 ft. over E. slope,
changing to SE. slope.

46.00 Spur ridge, bears N. 70° E. and S. 70° W.; desc. 23 ft. over N.
slope.

49.20 Point for the cor. of secs. 7, 8, 17, and 18, at proportionate
distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 14 ins. in the ground
to bedrock, over a 4 in. cross chiseled in the bedrock, in a mound
of stone, 5 ft. base, to top, with brass cap mkd.

T23SR6W
S 7 | S 8
S18 | S17
1957

Ed. 3/96 C.S. 63/04

from which

A fir, 14 ins. diam., bears N. 19° E., 46 lks. dist.,
mkd. T23S R6W S8 BT.

A fir, 16 ins. diam., bears S. 64° E., 67 lks. dist.,
mkd. T23S R6W S17 BT.

A fir, 12 ins. diam., bears S. 26° W., 34 lks. dist.,
mkd. T23S R6W S18 BT.

A fir, 12 ins. diam., bears N. 14° W., 57 lks. dist.,
mkd. T23S R6W S7 BT.

This cor. is established at head of ravine, course NE.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and
cedar. Undergrowth, salal, vine maple, and poison oak.

From the cor. of secs. 8, 9, 16, and 17.

N. $88^\circ 24'$ W., bet. secs. 8 and 17.

Descend 481 ft. over steep W. slope.

14.00 Creek, 7 lks. wide, course N.; asc. 650 ft. over steep E. slope.

34.60 Road, unimproved, 20 lks. wide and ridge, bears N. and S.; desc.
93 ft. over W. slope.

42.78 Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 17, at proportionate
distance; there is no remaining evidence of the original corner.