

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS 32.90	Edge of timber, bears E. and W.; asc. 73 ft. along broken W. slope.
50.37	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> $\frac{1}{4}$ \uparrow S6 S5 \downarrow 1955 </div> <p>from which</p> <p>An iron post, 3 ft. long, 3 ins. diam., set 30 ins. in the ground for a reference monument, bears East, 50 lks. dist., with brass cap mkd. $\frac{1}{4}$ S5 RM 1955 with an arrow pointing to the true corner.</p> <p>An iron post, 3 ft. long, 3 ins. diam., set 30 ins. in the ground for a reference monument, bears West, 50 lks. dist., with brass cap mkd. $\frac{1}{4}$ S6 RM 1955, with an arrow pointing to the true corner.</p> <p>Ascend 98 ft. along W. slope.</p>
72.70	Ridge, bears N. 20° W. and S. 20° E., edge of burn, bears N. 20° W. and S. 20° E.; trail, bears N. 20° W. and S. 20° E.; desc. 97 ft. along broken E. slope.
82.13	Spur, slopes N. 70° E.; desc. 263 ft. over N. slope.
86.80	Creek, 2 lks. wide, course N. 50° E.; desc. 7 ft. along E. slope.
94.86	Spur, slopes N. 10° E.; desc. 396 ft. over steep N. slope.
104.26	<p>The standard cor. of secs. 5 and 6, on the N. bdy. of the Tp.</p> <p>Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, vine maple, madrone, alder, and arrow-wood.</p>

General Description

Township 23 South, Range 6 West, is located approximately six miles southwest of Drain, Ore., and three miles west of Yoncalla, Ore. The elevation of the township ranges from about 400 ft. to 2,500 ft. above sea level. The highest point in the township, located on Yellow Butte, is occupied by a Western Lane Fire Protective Association lookout, elevation 2,454 ft. above sea level. This township is characterized by many, steep, choppy, and brushy spurs and ridges.

Portions of secs. 1, 2, 6, 25, and 36, are under cultivation, with the predominant interest in the grazing of cattle and sheep. The soil is primarily clay, varying from a light mantle on the steeper slopes, underlain by bedrock of sandstone, to considerable depth on the lower slopes.

Brush Creek drains the northwest portion of the township, Yellow Creek, the south and southeast half of the township, and Billy Creek the northeast quarter of the township. These streams reach flood stage quickly and have caused severe damage through erosion.