

BLM Rehab Surveyor's Record, Douglas County, Oregon  
13

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 26 S., R. 2 W.

CHAINS

Land, mountainous. Soil, rocky clay and clay loam. Timber, fir, hemlock, sugar pine, cedar, madrone, chinquapin, maple, alder, dogwood, oak and yew; undergrowth, salal, vine maple, rhododendron, poison oak, manzanita, hazel, huckleberry and blackberry.

N. 1°14' E., along the W. bdy. of sec. 15.

Ascend 261 ft. over S. slope, through scattering timber and light undergrowth.

5.30 Top of bluff, 210 ft. high, edge bears E. and W.; asc. 40 ft. over S. slope, along W. edge of logged area.

13.22 Cor. No. 1 of Tract 37, on the W. bdy. of sec. 15, monumented with an iron post, 1 in. diam., firmly set, 8 ins. above ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

		T 26 S
S 16		R 2 W
1		S 15
TR 37		1918

See Vol. 54 Page 21127-8  
for 2002 BLM Rehab  
(Adds 1 new BT)

from which the original bearing tree

A sawed fir stump, 22 ins. diam., bears S. 74° W., 50 lks. dist., with faint evidence of an old face.

add two new bearing trees

A fir, 12 ins. diam., bears N. 84° W., 34 lks. dist., mkd. AP S16 BT.

A cedar, 6 ins. diam., bears S. 62° W., 61 lks. dist., mkd. AP1 TR37 BT.

N. 1°06' E., beginning new measurement.

Ascend 106 ft. over S. slope, through logged area.

13.00 Top of ascent, slopes E.; desc. 80 ft. over NW. slope.

13.70 Three-wire transmission line, bears E. and W.

15.00 Three-wire transmission line, bears E. and W.

16.10 Dirt access road, 10 lks. wide, bears E. and W.

18.45 Dirt access road, 15 lks. wide, bears NE. and SW.

20.70 Foot of descent, slopes W.; asc. 69 ft. over S. slope.

26.65 Point for the  $\frac{1}{4}$  sec. cor. of sec. 15 only, at midpoint on the W. bdy. of sec. 15.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 26 S	R 2 W
	$\frac{1}{4}$
	S 15
1959	

FND. OK 6-99 BY K. DeGroot  
M131-08

from which