

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 33 S., R. 6 W.

CHAINS

from which new bearing trees:

A fir, 9 ins. diam., bears N. 78° E., 28 lks. dist.,
mkd. T33S R6W S35 BT.

A pine, 9 ins. diam., bears S. $62\frac{1}{2}^{\circ}$ E., 56 lks. dist.,
mkd. T34S R6W S2 BT.

A fir, 20 ins. diam., bears S. $69\frac{3}{4}^{\circ}$ W., 60 lks. dist.,
mkd. T34S R6W S3 BT.

A fir, 9 ins. diam., bears N. 70° W., 36 lks. dist.,
mkd. T33S R6W S34 BT.

N. $0^{\circ} 38'$ E., bet. secs. 34 and 35, marking and blazing the true line.

Ascend 65 ft. over SW. slope, through heavy timber and dense undergrowth.

- 4.26 Spur, slopes N. 20° W.; desc. 400 ft. over north slope.
- 14.10 Stream, 1 lk. wide, course NW.; asc. 120 ft. over SW. slope.
- 18.95 Spur, slopes NW.; desc. 135 ft. over NW. slope.
- 24.35 Draw, drains W.; asc. 40 ft. over SW. slope.
- 27.95 Spur, slopes W.; desc. 205 ft. over NW. slope.
- 37.25 Draw, drains N. 55° W.; asc. 28 ft. over SW. slope.
- 39.40 Spur, slopes W.; desc. slightly over NW. slope.
- 40.10 Point for the $\frac{1}{4}$ sec. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins diam., 22 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$
 S 34 | S 35
 T33S R6W
 1958

from which

A fir, 9 ins. diam., bears S. $54\frac{3}{4}^{\circ}$ E., 33 lks. dist.,
mkd. $\frac{1}{4}$ S35 BT.

A fir, 8 ins. diam., bears S. $15\frac{1}{2}^{\circ}$ W., 31 lks. dist.,
mkd. $\frac{1}{4}$ S34 BT.

Descend 45 ft. over NW. slope.

- 43.95 Mackin Gulch, 4 lks. wide, course SW.; asc. 580 ft. over SE. slope.
- 80.20 Point for the cor. of secs. 26, 27, 34, and 35, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

T33S R6W
 S 27 | S 26
 S 34 | S 35
 1958

from which