

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 33 S., R. 6 W.

CHAINS

T33S R6W
 $\frac{S\ 30}{S\ 31} | \frac{S\ 29}{S\ 32}$
 1958

from which new bearing trees

A fir, 6 ins. diam., bears N. 66° E., 36 lks. dist.,
 mkd. T33S R6W S29 BT.

A madrona, 4 ins. diam., bears S. 18° E., 61 lks. dist.,
 mkd. T33S R6W S32 BT.

A madrona, 4 ins. diam., bears S. 71° W., 36 lks. dist.,
 mkd. T33S R6W S31 BT.

A fir, 6 ins. diam., bears N. 29½° W., 52 lks. dist.,
 mkd. T33S R6W S30 BT.

Land, mountainous. Soil, rocky clay. Timber, fir, pine, and madrone;
 undergrowth, hazel, arrowwood and poison oak.

From the cor. of secs. 26, 27, 34, and 35.

S. 88° 33' W., bet. secs. 27 and 34.

Ascend 125 ft. over broken SE. slope, through heavy timber and
 dense undergrowth.

19.88

Point for the E. 1/16 sec. cor. of secs. 27 and 34.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the
 ground, with brass cap mkd.

E 1/16 $\frac{S\ 27}{S\ 34}$
 T33S R6W
 1958

from which

A fir, 15 ins. diam., bears N. 28° W., 27 lks. dist., mkd.
 E 1/16 S27 BT.

A fir, 20 ins. diam., bears S. 29° W., 27 lks. dist., mkd.
 E 1/16 S34 BT.

Ascend 145 ft. over SE. slope.

39.76

Point for the ¼ sec. cor. of secs. 27 and 34, at proportionate
 distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the
 ground, with brass cap mkd.

¼ $\frac{S\ 27}{S\ 34}$
 T33S R6W
 1958

from which

A fir, 8 ins. diam., bears N. 27½° E., 50 lks. dist.,
 mkd. ¼ S27 BT.

A fir, 18 ins. diam., bears S. 20° E., 32 lks. dist.,
 mkd. ¼ S34 BT.

Ascend 255 ft. over SE. slope.

58.00

Spur, slopes S.; desc. 515 ft. over SW. slope.