

County Surveyor's Record, Douglas County, Oregon

12777

Dependent Resurvey, Portion of Subdivisional Lines, T. 32 S., R. 4 W.

CHAINS

Ascend 650 ft. over SW. slope, through timber and undergrowth.

38.00

Spur, slopes SW.; desc. slightly over NW. slope.

40.62

Point for the $\frac{1}{4}$ sec. cor. of secs. 3, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, with brass cap marked

$\frac{1}{4}$ S 3
 T32S
 R4W
 1959

from which

A cedar, 16 ins. diam., bears N. 74° E., 12 lks. dist., marked $\frac{1}{4}$ S3 BT.

A fir, 14 ins. diam., bears S. 35° E., 53 lks. dist., marked $\frac{1}{4}$ S3 BT.

Descend 745 ft. over NW. slope.

76.30

Branch, 2 lks. wide, course W.; asc. 75 ft. over SW. slope.

81.24

The cor. of secs. 3, 4, 33 and 34, on the N. bdy. of the Tp., determined at record bearing and distance from the remaining original bearing trees marked by Byars in 1871:

A fir, 40 ins. diam., bears N. 80° E., 32 lks. dist., marked T31S R4W S34 BT on bark.

A fir, 14 ins. diam., bears S. 48° E., 7 lks. dist., marked S3 on open blaze.

and bearing trees marked by Nicklin in 1897

An ash, 10 ins. diam., bears S. 77° W., 47 lks. dist., marked S4 on open blaze.

A fir, 20 ins. diam., bears N. 45° W., 42 lks. dist., marked with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, with brass cap marked

T32S R4W
 S 33 | S 34
 S 4 | S 3
 T32S
 1959

Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, pine, cedar, madrona and chinquapin; undergrowth, manzanita, huckleberry and rhododendron.

From the cor. of secs. 3 and 4, on N. bdy of sec. 10.

S. 89° 30' W., along the S. bdy. of sec. 4.

Descend 80 ft. over SW. slope, through timber and undergrowth.

6.40

Draw, drains S.; asc. 15 ft. over SE. slope.

8.15

The closing cor. of secs. 9 and 10, hereinafter described.

Ascend slightly over SE. slope.