

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 32 S., R. 4 W.

CHAINS

- 9.16 Spur, slopes S.; desc. 230 ft. over SE. slope.
- 23.45 Whitehorse Creek, 20 lks. wide, course NW.; asc. 65 ft. over NE. slope.
- 29.45 Dirt road, 10 lks. wide, bears NW. and SE.
- 39.36 The $\frac{1}{4}$ sec. cor. of sec. 4 only, determined at record bearing and distance from the original bearing trees marked by Byars in 1871:
- A sawed fir stump, 16 ins. diam., bears N. 22° W., 30 lks. dist., marked BT on bark.
- A fir, 40 ins. diam., bears South, 7 lks. dist., marked $\frac{1}{4}$ S BT. on bark.
- At the corner point
- Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 20 ins. in the ground, with brass cap marked
- $\frac{1}{4}$ S 4
T32S R4W
1959
- from which new bearing trees
- A fir, 12 ins. diam., bears N. 3 $\frac{1}{4}$ ° E., 168 lks. dist., marked $\frac{1}{4}$ S4 BT.
- A fir, 14 ins. diam., bears N. 49 $\frac{1}{2}$ ° E., 76 lks. dist., marked $\frac{1}{4}$ S4 BT.

(Restoring the 1897 survey by Carl S. Nicklin)

From the cor. of secs. 10, 11, 14 and 15, determined at record bearing and distance from the remaining original bearing trees:

- A sawed fir stump, 24 ins. diam., bears N. 31° E., 78 lks. dist., marked BT on opened blaze.
- A rotted fir stump, 24 ins. diam., bears S. 72° E., 49 lks. dist., no marks remaining.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 14 ins. in the ground to solid rock, and in mound of stone, 3 ft. base, to top, with brass cap marked

T32S R4W
S 10 | S 11
S 15 | S 14
1959

from which new bearing trees

- A fir, 6 ins. diam., bears N. 26° E., 67 lks. dist., marked T32S R4W S11 BT.
- A fir, 10 ins. diam., bears S. 3° E., 82 lks. dist., marked T32S R4W S14 BT.
- A fir, 5 ins. diam., bears S. 24° W., 17 lks. dist., marked T32S R4W S15 BT.