

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 32 S., R. 4 W.

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap marked

$$\begin{array}{r} S\ 4 \\ \hline S\ 9\ S\ 10 \\ T32S\ R4W \\ E\ C \\ 1959 \end{array}$$

from which

A fir, 14 ins. diam., bears S. 32½° E., 45 lks. dist., marked T32S R4W S10 CC BT.

A fir, 14 ins. diam., bears S. 29° W., 55 lks. dist., marked T32S R4W S9 CC BT.

From this point the cor. of secs. 3 and 4, bears N. 89°.30' E., 8.15 chs. dist.

Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, pine, cedar, madrona and chinquapin; undergrowth, manzanita, huckleberry and rhododendron.

From the cor. of secs. 3 and 4, on N. bdy. of sec. 10.

N. 89° 50' E., along the S. bdy. of sec. 3.

Ascend slightly over SW. slope, through timber and undergrowth.

1.10 Spur, slopes S.; desc. 90 ft. over SE. slope.

7.40 Branch, 1 lk. wide, course S.; asc. 375 ft. over broken SW. slope.

31.625 Point for the ¼ sec. cor. of sec. 10, at midpoint between the closing cor. of secs. 9 and 10, and the closing cor. of secs. 3 and 10.

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap marked

$$\begin{array}{r} \frac{1}{4}\ S\ 10 \\ T32S\ R4W \\ 1959 \end{array}$$

from which

A madrona, 6 ins. diam., bears S. 72° E., 28 lks. dist., marked ¼ S10 BT.

A fir, 10 ins. diam., bears S. 57½° W., 10 lks. dist., marked ¼ S10 BT.

Ascend 120 ft. over broken SW. slope.

40.00 Point for the ¼ sec. cor. of sec. 3, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap marked

$$\begin{array}{r} \frac{1}{4}\ S\ 3 \\ T32S\ R4W \\ 1959 \end{array}$$

from which

A madrona, 7 ins. diam., bears N. 11° E., 12 lks. dist., marked ¼ S3 BT.