

Dependent Resurvey of a Portion of the Subdivisional Line., T. 29 S., R. 7 W.

CHAINS

Ascend 170 ft. over E. slope, changing to NE. slope.

52.50 Spur ridge, bears NE. and SW.; desc. 150 ft. over NW. slope.

65.50 Head of ravine, course N.; asc. 300 ft. over broken NE. slope.

86.06 The cor. of secs. 11, 12, 13 and 14.

Land, mountainous. Soil, rocky clay. Timber, fir, cedar, maple, madrone and alder; undergrowth, vine maple, hazel, arrowwood, Oregon grape and fern.

N. 0° 44' W., bet. secs. 11 and 12.

Descend 20 ft. over broken NE. slope, through heavy timber and dense undergrowth.

1.00 Spur, slopes N. 15° E.; descend 710 ft. over NW. slope.

30.00 Stream, 3 lks. wide, course N. 60° E.; asc. 80 ft. over SE. slope.

31.00 Graded road, 20 lks. wide, bears NE. and SW.

34.00 Spur, slopes E.; descend 40 ft. over NE. slope.

35.80 Ravine, drains SE.; asc. 110 ft. over S. slope.

39.345 Point for the $\frac{1}{4}$ sec. cor. of secs. 11 and 12, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

T29S R7W

$\frac{1}{4}$
S 11 | S 12

1957

from which

A fir, 8 ins. diam., bears N. 50° E., 50 lks. dist., marked $\frac{1}{4}$ S12 BT.

A madrone, 40 ins. diam., bears S. 5° W., 74 lks. dist., marked $\frac{1}{4}$ S11 BT.

Ascend 500 ft. over S. slope, changing to SE. slope.

66.05 Ridge, bears N. 80° E. and S. 80° W.; desc. 335 ft. over N. slope, changing to broken NW. slope.

78.69 The cor. of secs. 1, 2, 11 and 12, monumented with an iron post, 2 ins. diam., extending 8 ins. above ground, firmly set, with brass cap marked and witnessed as described in the official record.

Land, mountainous. Soil, rocky clay. Timber, fir, cedar, pine, oak, maple, madrone and alder; undergrowth, vine maple, hazel, arrowwood, poison oak and fern.

From the cor. of secs. 11, 12, 13 and 14.

S. 89° 37' W., bet. secs. 11 and 14.