

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 6 W.

CHAINS

A fir, 27 ins. diam., bears N. 26° W., 83 lks. dist.,
mkd. T29S R6W S28 BT..

The cor. is located on the E. bank of a stream, 5 lks. wide, 6 ins. deep, course NW.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, maple, oak, yew, madrona and alder.

Undergrowth, young timber, vinemaple, poison oak and ferns.

From the cor. of secs. 26, 27, 34, and 35.

S. 89°46' W., bet. secs. 27 and 34.

Ascend 75 ft. over NE. slope, through fir, maple, cedar and madrona timber.

2.20 Spur, slopes NE.; desc. 10 ft. over NW. slope.

3.20 Draw, drains NE.; asc. 120 ft. over NE., changing to E. slope.

10.00 Spur, slopes NE.; desc. 35 ft. over NW. slope.

14.40 Draw, drains NE.; asc. 105 ft. over NE. slope.

24.10 Spur, slopes N.; desc. 95 ft. over NW. slope, through open timber.

34.30 Draw, drains N.; asc. 10 ft. over NE. slope.

39.24 Point for the $\frac{1}{4}$ sec. cor. of secs. 27 and 34, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$ S 27
 $\frac{1}{4}$ S 34
T 29 S R 6 W
1958

from which

A fir, 23 ins. diam., bears N. 39 $\frac{1}{2}$ ° E., 41 lks. dist.,
mkd. $\frac{1}{4}$ S27 BT.

A fir, 19 ins. diam., bears S. 42° W., 22 $\frac{1}{2}$ lks. dist.,
mkd. $\frac{1}{4}$ S34 BT.

The $\frac{1}{4}$ sec. cor. is located on small spur, slopes N.

Descend 750 ft. over broken NW. slope.

78.48 The cor. of secs. 27, 28, 33, and 34.

Land, mountainous.

Soil, rocky clay.

Timber, fir, madrona, cedar, maple and oak.

Undergrowth, young timber, poison oak, hazel, vines and ferns.

N. 0°41' E., bet. secs. 27 and 28.

Ascend 185 ft. over SW. slope, through medium to scattering fir, oak, cedar and madrona timber.