

## County Surveyor's Record, Douglas County, Oregon

11

## Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 6 W.

CHAINS	
11.80	Spur, slopes W.; desc. 200 ft. over NW. slope.
21.20	Stream, 2 lks. wide, 2 ins. deep, course N. 70° W., asc. 55 ft. over SW. slope, to spur.
23.70	Dirt road, 15 lks. wide, bears E. and W.; continue ascent over nearly open land.
30.00	Spur, slopes W.; desc. 105 ft. over NW. slope.
37.20	Spring branch, 1 lk. wide, flows W.; asc. 25 ft. over SW. slope.
40.31	The $\frac{1}{4}$ sec. cor. of secs. 27 and 28, monumented with an iron post, 1 in. diam., 10 ins. above ground, firmly set, with brass cap mkd. County Surveyors $\frac{1}{4}$ S 28 27 T29S R6W 1954 Office, from which the original bearing trees: <p style="margin-left: 40px;">A madrona, dead, down and rotted, bears N. 42<math>\frac{1}{2}</math>° E., 115 lks. dist., no marks remain. (Record bearing N. 50° E.)</p> <p style="margin-left: 40px;">A white oak, 34 ins. diam., bears N. 32° W., 31 lks. dist., mkd. with illegible scribe marks.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2<math>\frac{1}{8}</math> ins. diam., 20 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <math display="block">\begin{array}{c} \frac{1}{4} \\ \text{S 28}   \text{S 27} \\ \text{T 29 S}   \text{R 6 W} \\ 1958 \end{array}</math> </div> <p>from which a bearing tree marked by the County Surveyor:</p> <p style="margin-left: 40px;">A fir, 20 ins. diam., bears N. 40° E., 23<math>\frac{1}{2}</math> lks. dist., mkd. <math>\frac{1}{4}</math> S27 CS BT.</p> <p>and a new bearing tree:</p> <p style="margin-left: 40px;">A white oak, 11 ins. diam., bears S. 29° W., 37 lks. dist., mkd. <math>\frac{1}{4}</math> S28 BT.</p> <p>Bury the County Surveyor's monument alongside the iron post.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 0°10' E., beginning new measurement.</p> <p>Ascend 30 ft. along broken W. slope, through scattering timber.</p>
23.30	Spur, slopes NW.; desc. 200 ft. over NE. slope.
27.70	Dirt road, 15 lks. wide, bears N. 70° W. and S. 70° E.
34.00	Stream, 1 lk. wide, course NW.; desc. 35 ft. over NW. slope.
36.46	Woven wire fence, bears E. and W.
38.05	The cor. of secs. 21, 22, 27, and 28, perpetuated with an iron pipe, $\frac{3}{4}$ in. diam., 6 ins. above ground, firmly set. This cor. was established by Ford, in 1854. The Douglas County records show that John Markham, C. E. found the iron pipe, in 1950, and two bearing trees, previously marked by a County Surveyor. I find no record of the previous reestablishment. The monument is locally accepted as marking the corner point, and is accepted as the best available evidence of the original corner position.
	At the corner point