

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 6 W.

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.

T 29 S R 6 W
 S 21 | S 22
 S 28 | S 27
 1958

from which a tree found by Markham:

A fir snag, 20 ins. diam., bears S. 29½° E., 82 lks. dist., mkd. S27 BT.

and trees marked by Markham in 1950:

A fir, 22 ins. diam., bears N. 39° E., 79 lks. dist., mkd. BT.

A fir, 17 ins. diam., bears East, 58 lks. dist., mkd. with illegible scribe marks.

A fir, 42 ins. diam., bears N. 11° W., 11 lks. dist., mkd. S21 2880 on bark blaze.

and new bearing trees:

A fir, 25 ins. diam., bears N. 42° E., 99 lks. dist., mkd. T29S R6W S22 BT.

A fir, 7 ins. diam., bears S. 22° E., 91 lks. dist., mkd. T29S R6W S27 BT.

A fir, 30 ins. diam., bears S. 11¼° W., 141 lks. dist., mkd. T29S R6W S28 BT.

A fir, 42 ins. diam., bears N. 11° W., 11 lks. dist., mkd. T29S R6W S21 BT.

Bury the iron pipe alongside the corner post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, oak and madrona.

Undergrowth, young timber, scrub oak, poison oak, ferns and grass.

From the cor. of secs. 22, 23, 26, and 27.

N. 89°10' W., bet. secs. 22 and 27.

Descend 85 ft. over broken NW. slope, through medium fir, cedar and madrona timber.

7.30 East Fork of Willis Creek, 5 lks. wide, 6 ins. deep, course NE.; asc. 100 ft. over broken NE. slope, through heavy timber.

17.80 Stream, 2 lks. wide, course NE.; asc. 30 ft. over NE. slope.

19.32 Point for the E 1/16 sec. cor. of secs. 22 and 27.

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.

E 1/16 S 22
 S 27
 T 29 S R 6 W
 1958