

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 6 W.

CHAINS

A maple, 12 ins. diam., bears N. 56° W., 82 lks. dist.,
mkd. $\frac{1}{4}$ S19 BT.

Ascend 100 ft. over SW. slope, through medium timber.

45.30 Spur, slopes W.; desc. 205 ft. over NW. slope.

53.30 Rice Creek Road, 30 lks. wide, bears NE. and SW.; enter open field
along road; desc. 15 ft. over NW. slope.

58.74 Point for the N. 1/16 sec. cor. of secs. 19 and 20.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground,
with brass cap mkd.

N 1/16
S 19 | S 20
T 29 S | R 6 W
1958

from which

An oak, 12 ins. diam., bears N. 30° E., 443 lks. dist.,
mkd. N 1/16 S20 BT.

A cottonwood, 7 ins. diam., bears N. 69° W., 183 lks. dist.,
mkd. N 1/16 S19 BT on bark blaze.

Descend 15 ft. over NW. slope, over open land.

61.80 Rice Creek, 15 lks. wide, 6 ins. deep, course NE.; asc. 75 ft.
over SE. slope.

67.76 Woven wire fence, bears E. and W.; enter scattering timber.

71.50 Spur, slopes E.; desc. 16 ft. over NE. slope.

72.90 Draw, drains E.; asc. 120 ft. over SE. slope, to sec. cor.

74.80 Dirt road, 10 lks. wide, bears E. and W.

78.32 Point for the cor. of secs. 17, 18, 19, and 20, at proportionate
distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the
ground, with brass cap mkd.

T 29 S R 6 W
S 18 | S 17
S 19 | S 20
1958

from which

A fir, 18 ins. diam., bears N. 8° E., 45 lks. dist.,
mkd. T29S R6W S17 BT.

A madrona, 4 ins. diam., bears S. 63° E., 19 lks. dist.,
mkd. T29S R6W S20 BT.

A fir, 25 ins. diam., bears N. 37° W., 36 lks. dist.,
mkd. T29S R6W S18 BT.

There is no suitable tree available in sec. 19.