

## County Surveyor's Record, Douglas County, Oregon

## Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 6 W.

CHAINS  
79.54

The cor. of secs. 17, 18, 19, and 20.

Land, mountainous.

Soil, rocky clay.

Timber, fir, pine, oak, cedar, madrona, maple and chinquapin.

Undergrowth, young timber, poison oak, hazel, arrowwood, berry and vines.

N. 89°40' W., bet. secs. 18 and 19.

Ascend 130 ft. over SE. slope, through medium timber.

3.20 Dirt road, 10 lks. wide, bears NW. and SE.

10.20 Spur, slopes S.; desc. 140 ft. over SW. slope.

15.10 Draw, drains S.; asc. 65 ft. over SE. slope.

18.20 Spur, slopes S.; woven wire fence, bears N. and S.; desc. 15 ft. over SW. slope.

19.78 Point for the E 1/16 sec. cor. of secs. 18 and 19.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} \text{E } 1/16 \frac{\text{S } 18}{\text{S } 19} \\ \text{T } 29 \text{ S } \text{R } 6 \text{ W} \\ 1958 \end{array}$$

from which

A cedar, 6 ins. diam., bears N. 81° E., 75 lks. dist., mkd. E 1/16 S18 BT.

A fir, 12 ins. diam., bears S. 21° E., 30 lks. dist., mkd. E 1/16 S19 BT.

Descend 30 ft. over SW. slope.

22.20 Draw, drains SE.; asc. 370 ft. over SE. slope.

39.56 Point for the ¼ sec. cor. of secs. 18 and 19, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} \frac{1}{4} \frac{\text{S } 18}{\text{S } 19} \\ \text{T } 29 \text{ S } \text{R } 6 \text{ W} \\ 1958 \end{array}$$

from which

A fir, 5 ins. diam., bears N. 53° W., 12 lks. dist., mkd. ¼ S18 BT.

A fir, 5 ins. diam., bears S. 5½° E., 4 lks. dist., mkd. ¼ S19 BT.

Ascend 110 ft. over SE. slope, changing to NE. slope.

45.80 Ridge, bears NE. and S.; desc. 330 ft. over broken NW. slope.

71.26 Stream, 1 lk. wide, course N.; asc. 180 ft. over NE. slope.