

County Surveyor's Record, Douglas County, Oregon

1884B

SOUTH BOUNDARY, T. 28 S., R. 9 W., Willamette N.

CHAINS	
	South Boundary T. 28 S., R. 9 W., W. N.
	After considerable search, being unable to find the $\frac{1}{4}$ post - reported as set - between Sections 3 and 34, from the post, still standing, at the corner of Sections 2, 3, 34 and 35, the bearing trees of which (still standing) agree with the government note s, (except that the("chinkapin" is a "Cedar"), to-wit:
	A Fir, 15 in. diam. bears, S. 10° E. 15 lks.
	A Fir, 15 " " bears S. 58° W. 32 lks.
	A Fir, 36" " bears N. 38° E. 33 lks.
	A Chinkapin, 12" bears N. 82° W. 27 lks.
	Run West setting temporary posts every 40 chains, at 4 miles and 2.94 chains intersected the west boundary 2.86 chains North of the Township Corner. My correction, therefore, was 70 links to each mile and the course of the line should be N. 89° 30' E., Hence, from the Township Corner, I run - - - - -
	North 89° 30' East, on true line along the South Boundary of Section 31. Variation 20° 15' E.
1.60	Brook, 3 links wide, runs N. W., Ascend mountain side.
24.00	Summit mountain N.
42.94	Set Post, 4 ft. long, 4 in diam, over ft. in ground, for $\frac{1}{4}$ section post, from which
	A Hemlock 18 in. diam. bears S. 76° E., 24 links.
	A Fir 48 in. diam. bears N. 25° W., 90 links.
53.00	Ridge, N. NE
60.00	Ridge, N. NE
76.00	Brook, 3 links wide, runs N. N.E.
82.94	Set Post, 4 ft. long, 6 in. diam, one ft. in the ground for corner of Sections 5, 6, 31 and 32, from which
	A Fir, 50 in. diam, bears N. 12° E., 19 links.
	A Hemlock, 18 in. diam. " S. 24° E., 18 links.
	A Hemlock, 8 in. diam. " S. 52° W., 52 links.
	A Fir 40 in. diam. " N. 75° W., 37 links.
	Land mountainous and broken. Soil third rate. Timber tolerable, Fir, Hemlock and Cedar
	August 19, 1875
	North 89° 30' East, on true line, along the South boundary of Section 32. Variation 20° 15' E.
38.00	Summit of mountain, N. E.