

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of the E. Bdy., T. 28 S., R. 9 W.

CHAINS

Deposit axle alongside iron post.

N. $0^{\circ} 01'$ W., beginning new measurement.

Descend 93 ft. over NE. slope, through logged area with scattered timber and dense undergrowth.

- 10.53 Dirt access road, 15 lks. wide, bears N. 60° W. and S. 60° E.
- 11.19 Lake creek, 10 lks. wide, course S. 60° E.; asc. 109 ft. over S. slope.
- 16.75 Skid road, 15 lks. wide, bears N. 30° W. and S. 30° E.; leave logged area, edge bears N. 30° W. and S. 30° E., enter heavy timber.
- 20.08 Point for the N 1/16 sec. cor. of secs. 31 and 36.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 28 S	
N 1/16	
R 9 W	R 8 W
S 36	S 31
1959	

from which

A white fir, 10 ins. diam., bears S. $53\frac{1}{2}^{\circ}$ E., 60 lks. dist., mkd. N 1/16 S31 BT.A white fir, 8 ins. diam., bears S. $57\frac{1}{2}^{\circ}$ W., $4\frac{1}{2}$ lks. dist., mkd. N 1/16 S36 BT.

Ascend 116 ft. over S. slope.

- 32.15 Branch, 1 lk. wide, course S. 30° E.; asc. 80 ft. over S. slope.
- 40.16 Point for the cor. of secs. 25, 30, 31, and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 28 S	
R 9 W	R 8 W
S 25	S 30
S 36	S 31
1959	

from which

A fir, 7 ins. diam., bears N. $22\frac{1}{4}^{\circ}$ E., $51\frac{1}{2}$ lks. dist., mkd. T28S R8W S30 BT.A fir, 7 ins. diam., bears S. $31\frac{1}{2}^{\circ}$ E., 15 lks. dist., mkd. T28S R8W S31 BT.A fir, 15 ins. diam., bears S. 46° W., $67\frac{1}{2}$ lks. dist., mkd. T28S R9W S36 BT.A cedar, 11 ins. diam., bears N. $58\frac{3}{4}^{\circ}$ W., $53\frac{1}{2}$ lks. dist., mkd. T28S R9W S25 BT.