

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of the E. Bdy., T. 28 S., R. 9 W.

CHAINS

Land, rolling hills.
Soil, clay loam and rocky clay loam.
Timber, fir, hemlock, cedar, white fir, madrone, chinquapin, dogwood, yew, maple, and alder; undergrowth, salal, Oregon grape, vine maple, fern, arrowwood, rhododendron, huckleberry, and manzanita.

N. 0° 01' W., bet. secs. 25 and 30.

Ascend 728 ft. over S. slope, along W. edge of logged area, through scattered timber and undergrowth.

40.16 Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 28 S
 $\frac{1}{4}$
R 9 W | R 8 W
S 25 | S 30
1959

from which

A hemlock, 12 ins. diam., bears S. 39° E., 23 lks. dist., mkd. $\frac{1}{4}$ S30 BT.

A hemlock, 10 ins. diam., bears N. 39 $\frac{1}{2}$ ° W., 35 lks. dist., mkd. $\frac{1}{4}$ S25 BT.

Ascend 639 ft. over SW. slope, changing to S.

66.90 Foot of bluff, 197 ft. high, bears E. and W.

70.40 Spur, slopes N. 70° W.; desc. 32 ft. over NW. slope.

80.32 The cor. of secs. 19, 24, 25, and 30, perpetuated and recorded by J. W. Byron, Deputy County Surveyor in 1956, monumented with an iron post, 1 in. diam., firmly set, 14 ins. above ground with brass cap mkd.

COUNTY			
T 28 S			
R 9 W		R 8 W	
C	S	D	
O	24 19	CO	
O	25 30		
S	1957		
CO	OFFICE		

from which the original bearing trees

A fir, 50 ins. diam., bears N. 78° E., 31 lks. dist., with healed blaze. (Record bearing, N. 78° W.)

A rotted hemlock stump, 24 ins. diam., bears S. 50° E., 5 lks. dist.

A rotted fir stump, 40 ins. diam., bears S. 65° W., 5 lks. dist.

A down yew, 10 ins. diam., bears N. 32° W., 40 lks. dist., with old face.

and Deputy County Surveyor's bearing trees