

County Surveyor's Record, Douglas County, Oregon

T. 20 S., R. 7 W.

CHAINS

The following is the remonumentation of the one-quarter section corner of sections 19 and 20, township 20 south, range 7 west, of the Willamette Meridian, as provided for in the General Special Instructions, Group No. 350, Oregon, dated May 3, 1957, "Investigation of Collateral or Physical Evidence of Corner Positions and Accessories, Followed by Remonumentation of Corner Points, With New Accessories When Needed."

The remonumentation of the corner was requested by the Coos Bay District Manager, for administrative purposes of the Bureau of Land Management.

(Remonumentation of the Corner Established by Thomas E. Todd, in 1891)

The $\frac{1}{4}$ sec. cor. of secs. 19 and 20, mounmented with the remains of the original corner tree, the decayed shell of a fir stump, 45 ins. diam., with scribe marks $\frac{1}{4}$ S visible on the E. face, (Record, W. face) from which the remains of the original bearing trees:

A rotted fir stump, size indeterminate, bears N. 86° E., 32 lks. dist., with no marks remaining.

A rotted fir stump, 30 ins. diam., bears N. 45° W., 21 lks. dist., with scribe marks BT visible in negative on the overgrowth.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, inside the shell of the original corner tree, with brass cap mkd.

$\frac{1}{4}$
S 19 | S 20
T20S R7W
1960

from which new bearing trees:

A fir, 13 ins. diam., bears S. 57° E., 148 lks. dist., mkd. $\frac{1}{4}$ S20 BT.

A fir, 50 ins. diam., bears N. 2° W., 68 lks. dist., mkd. $\frac{1}{4}$ S19 BT.