

-4-
County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the S. Bdy., T. 19 S., R. 8 W.

CHAINS	<p>N. 89° 04' W., beginning new measurement.</p> <p>Descend 213 ft. over SW slope.</p> <p>4.55 Bottom of dry ravine, drains SW.; ascend 138 ft. over SE. slope.</p> <p>11.30 Top of small spur, slopes SE.; descend 77 ft. over SW. slope.</p> <p>14.85 Bottom of dry draw, drains SE.; ascend 151 ft. over SE. slope.</p> <p>18.40 Top of spur, slopes S.; descend 19 ft.</p> <p>19.60 Ascend 86 ft. over SE. slope.</p> <p>24.50 Top of ridge, bears NE. and SW.; descend 195 ft. over W. slope.</p> <p>30.40 Bottom of dry draw, drains SE.; ascend 54 ft. over SE. slope.</p> <p>33.40 Top of small spur, slopes S.; descend 47 ft. over SW. slope.</p> <p>35.55 Bottom of dry draw, drains S.; ascend 114 ft. over SE. slope.</p> <p>40.00 Point for the cor. of secs. 2, 3, 34, and 35, as determined from the remains of the original bearing trees:</p> <p style="padding-left: 40px;">A fir stump, bears S. 15½° E., 17 lks. dist.</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears S. 85° W., 31 lks. dist., showing a healed blaze facing the corner.</p> <p style="padding-left: 40px;">A fir, 22 ins. diam., bears N. 21° W., 108 lks. dist., showing a healed blaze facing the corner.</p> <p>At the corner point</p> <p>Set an iron post, 3 ft. long, 2 ins. diam., 26 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td colspan="2" style="border: none;">T19S R8W</td> </tr> <tr> <td style="border: none; padding: 0 5px;">S 34</td> <td style="border: none; padding: 0 5px;">S 35</td> </tr> <tr> <td style="border: none; padding: 0 5px;">S 3</td> <td style="border: none; padding: 0 5px;">S 2</td> </tr> <tr> <td colspan="2" style="border: none; text-align: center;">T20S</td> </tr> <tr> <td colspan="2" style="border: none; text-align: center;">1952</td> </tr> </table> </div> <p>from which</p> <p style="padding-left: 40px;">A hemlock, 10 ins. diam., bears N. 32° E., 122 lks. dist., mkd. T19S R8W S35 BT.</p> <p style="padding-left: 40px;">A fir, 57 ins. diam., bears S. 52½° E., 105 lks. dist., mkd. T20S R8W S 2 BT.</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears N. 38° W., 50 lks. dist., mkd. T19S R8W S34 BT.</p> <p>Land, mountainous.</p> <p>Soil, rocky clay with some sandstone.</p> <p>Timber, heavy fir, hemlock, cedar, alder, maple, dogwood, chinquapin, and madrona.</p> <p>Undergrowth, dense vine maple, hazel, arrowwood, salal, manzanita, poison oak, huckleberry, and bracken.</p>	T19S R8W		S 34	S 35	S 3	S 2	T20S		1952	
T19S R8W											
S 34	S 35										
S 3	S 2										
T20S											
1952											