

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the S. bdy., T. 19 S., R. 8 W.

CHAINS

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground with brass cap mkd.

T19S	R8W
S33	S34
S 4	S 3
T20S	
1952	

from which

A hemlock, 27 ins. diam., bears S. $55^{\circ} 45' W.$, 90 lks. dist. mkd. T20S R8W S 4 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, maple, cedar, alder dogwood, chinquapin, and madrona.

Undergrowth, vine maple, hazel, arrowwood, salal, huckleberry, manzanita, poison oak, and braken.

N. $89^{\circ} 27' W.$, between secs. 4 and 33.

Descend 231 ft. over NW. slope; through heavy timber and dense undergrowth.

- 8.10 Stream, 3 lks. wide, course NW.; ascend 64 ft. over NE. slope.
- 10.50 Top of small spur, slopes NW.; descend 256 ft. over NW. slope.
- 20.60 Stream, 3 lks. wide, course SW.; ascend 56 ft. over SE. slope.
- 29.15 Top of spur, slopes SW.; descend 136 ft. over SW. slope.
- 32.60 Stream, 3 lks. wide, course SW.; ascend 165 ft. over E. slope.
- 39.63 Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 33, as determined from the remains of the original bearing trees:

A fir, 60 ins. diam., bears N. $23^{\circ} E.$, 87 lks. dist., showing a healed blaze facing SW.A stump hole of an alder, bears S. $22^{\circ} E.$, 39 lks. dist.,

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground with brass cap mkd.

$\frac{1}{4}$	S 33
	S 4
1952	

from which

A maple, 10 ins. diam., bears S. $26\frac{1}{2}^{\circ} E.$, 46 lks. dist. $\frac{1}{4}$ S 4 BT.N. $88^{\circ} 43' W.$, beginning new measurement.

Ascend 104 ft. over NE. slope.