

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivision, T. 19 S., R. 8 W.

CHAINS

A fir, 10 ins. diam., bears N.  $39^{\circ} 45'$  E., 131 lks. dist., mkd. T19S R8W S15 BT.

A fir, 42 ins. diam., bears N.  $47^{\circ}$  W., 138 lks. dist., mkd. T19S R8W S16 BT.

Land, mountainous.

Soil, Clay and sandstone.

Timber, heavy fir, hemlock, cedar, alder, maple, chinquapin, dogwood, and madrona.

Undergrowth, dense vine maple, hazel, salal, huckleberry, arrowwood, manzanita, bracken, and Oregon grape.

N.  $0^{\circ} 49'$  E., between secs. 15 and 16.

Ascend 42 ft. over very broken W. slope; through heavy timber and dense undergrowth.

- 4.50 Spur, slopes NW.; descend 165 ft. over NW. slope.
- 8.45 A dry ravine, course N.  $70^{\circ}$  W.; ascend 21 ft.
- 11.30 A small spur, slopes NW.; descend 19 ft. over broken NW. slope.
- 12.75 A small stream, drains SW.; ascend 175 ft. over SW. slope.
- 15.75 A spur, slopes NW.; descend 149 ft. over NW. slope.
- 21.70 Ravine, drains NW.; ascend 160 ft. over SW. slope.
- 29.50 A spur, slopes NW.; descend 205 ft. over NW. slope.
- 34.60 Ravine, drains NW.; ascend 222 ft. along SW. slope.
- 41.21 Point for the  $\frac{1}{4}$  sec. cor. of secs. 15 and 16, as determined from the remains of the original bearing trees:
- A fir stump bears S.  $31\frac{1}{2}^{\circ}$  E., 91 lks. dist., at the base of which is an alder, 10 ins. diam., mkd.  $\frac{1}{4}$  S BT.
- A stump, apparently chinquapin, bears N.  $45^{\circ}$  W., 13 lks. dist.
- At the corner point
- Set an iron post, 3 ft. long, 1 in. diam. 27 ins. in the ground, with brass cap mkd.
- S 16 | S 15

1952
- from which
- A fir, 45 ins. diam., bears N.  $20^{\circ}$  E., 87 lks. dist., mkd.  $\frac{1}{4}$  S15 BT.
- A fir, 27 ins. diam., bears N.  $31^{\circ}$  W., 121 lks. dist., mkd.  $\frac{1}{4}$  S16 BT.
- 
- N.  $0^{\circ} 47'$  E., beginning new measurement.