

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivision, T. 19 S., R. 8 W.

CHAINS

- 35.42 An improved road, bears N. 30° E. and S. 30° W.
- 37.80 A shallow dry draw, drains SW.; ascend 15 ft. over gentle S. slope.
- 39.40 Top of ascent, falls SW.; thence on nearly level course over W. slope.

40.34 Point for the cor. of secs. 3, 4, 9 and 10 as determined from the remains of the original bearing trees:

A fir, 45 ins. diam., bears N. 21½° E., 40 lks. dist., showing a nearly healed blaze facing SW. (Record bearing, N. 21° E.)

A badly decayed fir stump bears S. 46½° E., 36 lks. dist., no marks distinguishable.

A fir, 43 ins. diam., bears N. 4½° W., 44 lks. dist., showing nearly healed blaze facing S.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins in the ground, with brass cap mkd.

T19S	R8W
S 4	S 3
S 9	S10
1952	

from which

A fir, 20 ins. diam., bears N. 72° E., 138 lks. dist., mkd. T19S R8W S3 BT.

A fir, 28 ins. diam., bears S. 25½° E., 80 lks. dist., mkd. T19S R8W S10 BT.

A fir, 30 ins. diam., bears S. 84½° W., 186 lks. dist. mkd. T19S R8W S9 BT.

A fir, 34 ins. diam., bears N. 55½° W., 57 lks. dist., mkd. T19S R8W S4 BT.

USGS Bench Mark bears N.44° 54' E., 25.098 chs. dist. plus. datum, 539 feet.

Land, mountainous.

Soil, rocky clay.

Timber, heavy fir, hemlock, cedar maple, alder, dogwood, and madrona.

Undergrowth, dense vine maple, hazel, arrowwood, salal, huckleberry, and bracken.

From the cor. of secs. 4, 5, 32 and 33, on the S. bdy. of Twp.

N. 0° 27' W., between secs. 32 and 33.

Over mountainous land; through heavy timber and dense undergrowth; ascend 239 ft. over very steep SW. slope.

- 6.00 Top of ridge, bears NW. and SE.; descend 427 ft. along steep NW. slope.

- 14.60 Stream, 3 lks. wide, course W.; ascend 300 ft. over steep, broken SW. slope.

- 26.65 Top of small spur, slopes W.; descend 143 ft. over NW. slope.