

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the subdivision, T. 19 S., R. 8 W.

CHAINS

- 30.60 Small draw, drains W.; cross low point of spur.
- 34.10 Small stream, $1\frac{1}{2}$ lks. wide, course SW.; ascend 270 ft. over steep S. slope.
- 40.30 Point for the $\frac{1}{4}$ sec. cor. of secs. 32 and 33 as determined from the remains of the original bearing trees:
- A fir, 55 ins. diam. bears W., 15 lks. dist., showing old blaze facing E.
- A fir stump bears E., 55 lks. dist., showing old axe scars.
- At the corner point
- Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.
- S 32 | S 33

1952
- from which
- A fir, 30 ins. diam., bears $N. 83^\circ E.$, 56 lks. dist., mkd. $\frac{1}{4}$ S33 BT.
-
- N. $0^\circ 08' E.$, beginning new measurement.
- Ascend 69 ft. over steep S. slope.
- 1.70 Top of divide between Esmond Creek and North Sisters Creek, bears E. and W.; descend 612 ft. over steep NW. slope.
- 16.10 Slope becomes less steep.
- 28.35 Bottom of ravine, drains NE.; ascend 78 ft. over SE. slope.
- 32.00 Top of low spur, slopes E.; descend 26 ft. over N. slope.
- 33.60 Trail to Twin Sisters Guard Station, bears NW. and SE.
- 34.50 Bottom of ravine, drains SW.; ascend 242 ft. over S. slope.
- 37.50 Slope changes to SW.
- 40.84 The cor. of secs. 28, 29, 32 and 33 as determined from the remains of the original bearing trees:
- A fir, 42 ins. diam., bears $S. 51^\circ E.$, 19 lks. dist. mkd. with a healed scar facing NW. (Record bearing, $S. 65\frac{1}{2}^\circ E.$)
- A fir, 35 ins. diam., bears $S. 45^\circ 45' W.$, 35 lks. dist., showing old scar facing NE. (Record bearing, $S. 48^\circ W.$)
- A fir, 47 ins. diam. bears $N. 84\frac{1}{4}^\circ W.$, 19 lks. dist., with old blaze facing E. (Record bearing, $N. 73^\circ W.$)
- At the corner point.
- Set an iron post, 3 ft. long, 2 ins. diam., 20 ins. in the ground to solid rock and in a mound of stone to top, with brass cap mkd.