


# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivision, T. 19 S., R. 8 W.

CHAINS

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 26 ins in the ground, with brass Cap mkd.



from which

A fir, 48 ins. diam., bears N. 32° E., 91 lks. dist., mkd.  
T19S R8W S16 BT.

An alder, 14 ins. diam., bears S. 73° 45' E., 57 lks. dist., mkd.  
T19S R8W S21 BT.

Land, mountainous, very broken on W. slope of Esmond Creek canyon.  
Soil, rocky clay.

Timber, heavy fir, hemlock, cedar, maple, alder, chinquapin,  
dogwood and madrona.

Undergrowth, dense vine maple, hazel, salmonberry, huckleberry,  
salal, rhododendron, bracken and Oregon grape.

From the cor. of secs. 15, 16, 21 and 22.


N. 89° 05' W., between secs. 16 and 21.

Over very broken mountainous land; through heavy timber and  
undergrowth; descend 77 ft. over steep W. slope.

- 1.93 A stream, 2 lks. wide, course NW.; ascend 338 ft. over steep NE. slope.
- 13.40 Top of spur, slopes N.; descend 324 ft. over steep NW. slope.
- 22.45 A dry draw, drains NW., ascend slightly along broken N. slope.
- 26.00 Top of spur, slopes NW.; descend 157 ft. over broken W. slope.
- 34.25 A stream, 3 lks. wide, course NW.; thence over nearly level bottom land.
- 37.60 A fir, 50 ins. diam., showing axe marks on E. and W. face.
- 38.77 Point for the  $\frac{1}{4}$  sec. cor. of secs. 16 and 21 as determined from the original bearing trees:
  - A fir, 55 ins. diam., bears N. 10° E., 31 lks. dist., with old blaze on SW. face.
  - A fir, 37 ins. diam., bears S. 19 $\frac{1}{2}$ ° W., 58 lks. dist., with old blaze on NE. face.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, with brass cap mkd.



from which