

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the E. Bdy., T. 19 S., R. 8 W.

CHAINS	<p>from which new bearing trees</p> <p>A fir, 18 ins. diam., bears S. <math>5\frac{1}{2}^{\circ}</math> W., 31 lks. dist., mkd. <math>\frac{1}{4}</math> S24 BT.</p> <p>A fir, 18 ins. diam., bears N. <math>40^{\circ}</math> W., 35 lks. dist., mkd. <math>\frac{1}{4}</math> S24 BT.</p> <hr/> <p>N. <math>0^{\circ} 22'</math> E., beginning new measurement.</p> <p>Descend 118 ft. over NE. slope.</p> <p>3.50 A branch, 2 lks. wide, course N. <math>70^{\circ}</math> W.; ascend 38 ft. over SW. slope.</p> <p>6.30 Top of ascent on W. slope; descend 105 ft. over NW. slope, changing to broken N. slope.</p> <p>11.20 A branch, 3 lks. wide, course N. <math>80^{\circ}</math> W.; asc. 31 ft. over SW. slope.</p> <p>13.25 A broad spur, slopes gradually N. <math>80^{\circ}</math> W.; descend 196 ft. over NE. slope, changing to steep N. slope.</p> <p>19.55 Left bank of Siuslaw River, 95 lks. wide, course N. <math>80^{\circ}</math> W.</p> <p>20.50 Right bank of Siuslaw River; ascend 50 ft. over gentle S. slope, through dense bracken and young fir timber.</p> <p>31.30 A dirt road, bears N. <math>80\frac{1}{2}^{\circ}</math> W. and S. <math>81\frac{1}{2}^{\circ}</math> E. N. peak of barn bears S. <math>72\frac{1}{2}^{\circ}</math> E.</p> <p>35.05 Point for the <math>\frac{1}{4}</math> sec. cor. of sec. 19 only, at midpoint on the W. bdy. of sec. 19.</p> <p>40.43 Point for the cor. of secs. 13 and 24, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap marked</p> <table style="margin-left: auto; margin-right: auto;"> <tr><td>T 19 S</td><td> </td><td>T 19 S</td></tr> <tr><td>S 13</td><td> </td><td>R 7 W</td></tr> <tr><td>S 24</td><td> </td><td>S 19</td></tr> <tr><td>R 8 W</td><td> </td><td></td></tr> <tr><td></td><td></td><td>1949</td></tr> </table> <p>from which</p> <p>An iron post, 3 ft. long, 2 ins. diam., set 30 ins. in the ground, for a reference monument, bears S. <math>45^{\circ}</math> E., 10 lks. dist., with brass cap marked T19S R7W S19 RM 1949 and an arrow pointing to the corner.</p> <p>A fir, 6 ins. diam., bears S. <math>11^{\circ} 45'</math> W., 72 lks. dist., marked T19S R8W S24 BT.</p> <p>A fir, 8 ins. diam., bears N. <math>78\frac{1}{4}^{\circ}</math> W., 112 lks. dist., marked T19S R8W S13 BT.</p> <p>An iron post, 3 ft. long, 2 ins. diam., set 30 ins. in the ground, for a reference monument, bears N. <math>45^{\circ}</math> W., 10 lks. dist. with brass cap marked T19S R8W S13 RM 1949 and an arrow pointing to the corner.</p> <p>Land, mountainous, rolling. Soil, sandy clay loam. Timber, fir, hemlock, maple, chinquapin, madrona, dogwood, &amp; cedar. Undergrowth, vine maple, arrowwood, hazel, willow, salal, bracken, slickleaf, manzanita, and young timber.</p>	T 19 S		T 19 S	S 13		R 7 W	S 24		S 19	R 8 W					1949
T 19 S		T 19 S														
S 13		R 7 W														
S 24		S 19														
R 8 W																
		1949														

N.  $0^{\circ} 22'$  E., along the E. bdy of sec. 13.

Ascend 159 ft. over gentle S. slope, changing to broken W. slope, through heavy young timber and dense undergrowth, logged over & burned.