

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the E. bdy., T. 19 S., R. 8 W.

CHAINS											
	N. 0° 10' W., beginning new measurement. Descend 178 ft. over N. slope.										
4.25	A branch, 4 lks. wide, course E.; ascend 184 ft. over SW. slope.										
10.45	A spur, slopes W.; descend 11 ft. over NW. slope.										
11.25	A ravine, course SW.; ascend 124 ft. over S. slope.										
15.50	A ridge, the divide bet. Siuslaw River and Wolf Creek, bears N. 80° E. and S. 80° W.; descend 168 ft. over N. slope.										
18.60	A ravine, course N. 25° E.; ascend 165 ft. over broken SE. slope.										
27.35	A spur, slopes N. 70° E.; descend 331 ft. over steep N. slope.										
33.80	A ravine, course E.; ascend 93 ft. over SE. slope.										
35.95	Point for the $\frac{1}{4}$ sec. co r. of sec. 7 only, at midpoint on the W. bdy. of sec. 7.										
36.80	A spur, slopes S. 80° E.; descend 24 ft. over NE. slope.										
38.45	A branch, 2 lks. wide, course E.; ascend 87 ft. over S. slope.										
40.25	The cor. of secs. 1 and 12, determined at the record bearing from the original SW. bearing tree and the complement of the record bearing and at the record distance from the original NW. bearing tree as follows: A fir, 30 ins. diam., bears S. 3° W., 39 lks. dist., plainly blazed and healed. (Record distance 19 lks.) A fir, 32 ins. diam., bears N. 63 $\frac{1}{2}$ ° W., 15 lks. dist., plainly blazed and healed. (Record bearing N. 26 $\frac{1}{2}$ ° W.) At the corner point Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap marked <table style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <tr> <td style="padding: 0 5px;">T 19 S.</td> <td style="border-left: 1px solid black; padding: 0 5px;">T 19 S</td> </tr> <tr> <td style="padding: 0 5px;">S 1</td> <td style="border-left: 1px solid black; padding: 0 5px;">R 7 W</td> </tr> <tr> <td style="padding: 0 5px;">S 12</td> <td style="border-left: 1px solid black; padding: 0 5px;">S 7</td> </tr> <tr> <td style="padding: 0 5px;">R 8 W</td> <td style="border-left: 1px solid black; padding: 0 5px;"></td> </tr> <tr> <td></td> <td style="border-left: 1px solid black; padding: 0 5px; text-align: center;">1949</td> </tr> </table> Land, mountainous Soil, sandy clay loam. Timber, fir, hemlock, maple, cedar, chinquapin, alder, madrona, yew, and dogwood. Undergrowth, vine maple, hazel, arrowwood, salmonberry, devil's-club, thimbleberry, salal and bracken.	T 19 S.	T 19 S	S 1	R 7 W	S 12	S 7	R 8 W			1949
T 19 S.	T 19 S										
S 1	R 7 W										
S 12	S 7										
R 8 W											
	1949										
	N. 0° 30' E., along the E. bdy. of sec. 1. Ascend 193 ft. over S. slope, through heavy timber and dense undergrowth.										
5.50	A ridge, bears E. and W.; descend 440 ft. over N. slope, changing to NW. slope.										
16.00	A branch, 3 lks. wide, course N. 85° W.; ascend 123 ft. over SW. slope.										
24.80	A spur, slopes N. 80° W.; descend 265 ft. over NW. slope.										
31.70	A branch, 3 lks. wide, course E.; ascend 73 ft. over S. slope.										
35.74	Point for the closing corner of secs. 6 and 7, T. 19 S., R. 7 W.										