

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 23 S., R. 1 W.

CHAINS

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 25 ins. in the ground, & in a mound of stone, 2 ft. base to top, with brass cap mkd.

T 23 S R 1 W
S 23 S 24
S 26 S 25
1960

from which

A fir, 13 ins. diam., bears S. 51° W., 67 lks. dist.,
mkd. T23S RLW S26 BT.

Deposit original corner stone alongside iron post,

Land, mountainous.

Soil, rocky and clay loam.

Timber, fir, hemlock, cedar, and madrona.

Undergrowth, reproduction, and vine maple.

From the cor. of secs. 24 and 25 only, on the E. bdy. of the Tp.,
monumented with an iron post, 2 ins. diam., supported in a mound
of stone, 3 ft. base, 2 ft. high, firmly set, marked and witnessed
as described in the official record.S. $88^{\circ} 38'$ W., bet. secs. 24 and 25.Descend 767 ft. over NW. slope, through scattering timber and dense
undergrowth.

28.95 Quartz Creek, 10 lks. wide, course NE.; asc. 324 ft. over SE. slope.

31.10 Quartz Creek road, gavelled, 30 lks. wide, bears NE. and SW.

40.19 Point for the $\frac{1}{4}$ sec. cor. of secs. 24 and 25, at proportionate distance;
there is no remaining evidence of the original corner.Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground,
and in a mound of stone, 2 ft. base, to top, with brass cap mkd.

T 23 S R 1 W
$\frac{1}{4}$ S 24
S 25
1960

from which

A fir, 37 ins. diam., bears N. 54° W., 48 lks. dist.,
mkd. $\frac{1}{4}$ S24 BT.A fir, 9 ins. diam., bears S. 37° W., 101 lks. dist.,
mkd. $\frac{1}{4}$ S25 BT.

Ascend 501 ft. over SE. slope.

60.285 Point for the W 1/16 sec. cor. of secs. 24 and 25.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the
ground, to bedrock, and in a mound of stone, $2\frac{1}{2}$ ft. base to top,
with brass cap mkd.

W 1/16	S 24
	—
	S 25
	1960