

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 23 S., R. 1 W.

CHAINS

N. 0° 35' E., beginning new measurement.

Ascend 22 ft. over SE. slope.

0.80 Top of ascent, slopes E.; desc. 154 ft. over NE. slope.

13.55 Bottom of descent, drains E.; asc. 114 ft. over SE. slope.

20.30 Spur, slopes NE.; desc. 722 ft. over NW. slope.

38.05 The cor. of secs. 22, 23, 26, and 27, monumented with the original basalt stone, 18 x 10 x 6 ins., firmly set, 10 ins. above the ground, marked with 2 notches on the S., and 2 notches on the E. edge, from which the original bearing trees:

A downed fir, 36 ins. diam., bears N.15° E., 40 lks. dist., with a healed blaze.

A fir, 28 ins. diam, bears S. 54° E., 29 lks. dist., with a healed blaze.

A fir, 30 ins. diam., bears S. 44° W., 97 lks. dist., with a healed blaze. (Record bearing and distance, S. 24° W., 125 lks. dist. Slope dist., 125 lks.)

A fir, 34 ins. diam., bears N. 26° W., 30 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a mound of stone, 2 ft. base to top, with brass cap mkd.

T 23 S R 1 W
S 22 S 23
S 27 S 26
1960

from which

A hemlock, 6 ins. diam., bears N. 75° E., 36 lks. dist., mkd. T23S RLW S23 BT.

A hemlock, 6 ins. diam., bears N. 32° W., 48 lks. dist., mkd. T23S RLW S22 BT.

Deposit original corner stone alongside iron post.

Land, mountainous.

Soil, rocky and clay loam.

Timber, fir, cedar, hemlock, and madrona.

Undergrowth, salal, vine maple, and reproduction.

From the cor. of secs. 23, 24, 25 and 26.

S. 88° 19' W., bet. secs. 23 and 26.

Ascend 392 ft. over SE. slope, through old growth timber and dense undergrowth.

14.20 Ridge, bears N. and S.; desc. 183 ft. over NW. slope.

19.63 Point for the E 1/16 sec. cor. of secs. 23 and 26.

Set an iron post, 28 ins. long, 2½ ins. diam., 18 ins. in the ground to bedrock, and in a mound of stone, 3 ft. base to top, with brass cap mkd.