

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 23 S., R. 1 W.

## CHAINS

From the cor. of secs. 11, 12, 13 and 14.

N. 81° 21' W., bet. secs. 11 and 14.

Descend 132 ft. along broken S. slope, through heavy timber and dense undergrowth.

15.20 Bottom of descent, slopes S.; asc. 133 ft. over SE. slope.

20.458 Point for the E 1/16 sec. cor. of secs. 11 and 14.

Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, &amp; in a mound of stone, 2 ft. base to top, with brass cap mkd.

$$E \frac{1}{16} \begin{array}{l} S \ 11 \\ S \ 14 \\ 1960 \end{array}$$

from which

A fir, 10 ins. diam., bears N. 19° E., 23 lks. dist.,  
mkd. E 1/16 S11 BT.A fir, 13 ins. diam., bears S. 31° W., 11 lks. dist.,  
mkd. E 1/16 S14 BT.

Ascend 335 ft. over SE. slope.

32.75 Ridge, bears NE. and SW.; desc. 87 ft. over NW. slope.

40.915 Point for the ¼ sec. cor. of secs. 11 and 14, at proportionate distance; there is no remaining evidence of the orig. corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground and in a mound of stone, 2½ ft. base to top, with brass cap mkd.

$$T \ 23 \ S \ R \ 1 \ W \\ \frac{1}{4} \begin{array}{l} S \ 11 \\ S \ 14 \\ 1960 \end{array}$$

from which

A fir, 6 ins. diam., bears N. 49½° W., 4 lks. dist.,  
mkd. ¼ S11 BT.A fir, 8 ins. diam., bears S. 49½° E., 46 lks. dist.,  
mkd. ¼ S14 BT.

Descend 604 ft. over NW. slope.

55.20 Creek, 4 lks. wide, course N.; asc. 188 ft. over NE. slope.

60.60 Spur, slopes N.; desc. 142 ft. over NW. slope.

67.50 Creek, 4 lks. wide, course N.; asc. 248 ft. over NE. slope.

81.83 The cor. of secs. 10, 11, 14 and 15.

Land, mountainous.

Soil, rocky and clay loam.

Timber, fir, cedar, hemlock, and madrone.

Undergrowth, salal, vine maple and reproduction.

From the cor. of secs. 26, 27, 34 and 35.

N. 87° 47' W., bet. secs. 27 and 34.