

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 23 S. R. 1 W.

CHAINS

At the corner point

Set an iron post, 38 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, and in a mound of stone, $2\frac{1}{2}$ ft. base to top, with brass cap mkd.

T 23 S R 1 W
 $\frac{1}{4}$
 S 20 | S 21
 1960

from which

A fir, 14 ins. diam., bears S. 38° E., 20 lks. dist., mkd. $\frac{1}{4}$ S21 BT.

A fir, 20 ins. diam., bears N. 32° W., 38 lks. dist., mkd. $\frac{1}{4}$ S20 BT.

Deposit original corner stone alongside iron post.

N. $1^\circ 03'$ W., beginning new measurement

Descend 6 ft. over NW. slope.

0.25 Ravine, drains W.; asc. 70 ft. over SW. slope.

3.50 Spur, slopes W.; desc. 123 ft. over NW. slope.

6.10 Creek, 2 lks. wide, course NW.; asc. 638 ft. over SW. slope.

32.60 Ridge, bears E. and W.; desc. 110 ft. over NW. slope.

33.00 Dirt access road, 20 lks. wide, bears NW. and SE.

38.82 The cor. of secs. 16, 17, 20 and 21, monumented with the original basalt stone, 14 x 8 x 6 ins., firmly set, 6 ins. above the ground, marked with 3 notches on the S. and 4 notches on the E. edge, from which the original bearing trees:

A fir, 18 ins. diam., bears N. 10° E., 69 lks. dist., with healed blaze.

A fir, 24 ins. diam., bears S. $22\frac{1}{2}^\circ$ E., 197 lks. dist., with healed blaze.

A fir, 30 ins. diam., bears S. $29\frac{1}{2}^\circ$ W., 191 lks. dist., with healed blaze. (Record distance 138 lks.)

A rotted fir snag, 20 ins. diam., bears N. 76° W., 275 lks. dist., with axe marks visible on bark.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 23 S R 1 W
 S 17 | S 16
 S 20 | S 21
 1960

from which

A fir, 8 ins. diam., bears N. 51° E., 29 lks. dist., mkd. T23S RLW S16 BT.