

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of Subdivisional Lines, T. 21 S., R. 4 W.

CHAINS											
	<p>A cedar, 53 ins. diam., bears S. $4\frac{1}{4}^{\circ}$ E., 39 lks. dist., mkd. with a nail stamped W on head and driven through the center of a 3 in. bronze disc mkd.: Reg. Engineer No. 2149.</p> <p>A fir, 15 ins. diam., bears S. $70\frac{3}{4}^{\circ}$ W., 64 lks. dist., mkd. with a nail stamped W on head and driven through the center of a 3 in. bronze disc mkd.: Reg. Engineer No. 2149.</p> <p>A fir, 11 ins. diam., bears N. 54° W., $18\frac{1}{2}$ lks. dist., mkd. with a nail stamped W on head and driven through the center of a 3 in. bronze disc mkd.: Reg. Engineer No. 2149.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td style="padding: 0 5px;">T 21 S</td> <td style="border-left: 1px solid black; padding: 0 5px;">R 4 W</td> </tr> <tr> <td style="padding: 0 5px;">S 35</td> <td style="border-left: 1px solid black; padding: 0 5px;">S 36</td> </tr> <tr> <td style="border-top: 1px solid black; padding: 0 5px;">S 2</td> <td style="border-left: 1px solid black; border-top: 1px solid black; padding: 0 5px;">S 1</td> </tr> <tr> <td style="padding: 0 5px;">T 22 S</td> <td></td> </tr> <tr> <td colspan="2" style="padding: 0 5px;">1958</td> </tr> </table> </div> <p>from which</p> <p>A fir, 12 ins. diam., bears N. $79\frac{3}{4}^{\circ}$ E., 112 lks. dist., mkd. T21S R4W S36 BT.</p> <p>A fir, 16 ins. diam., bears S. $74\frac{1}{4}^{\circ}$ E., 68 lks. dist., mkd. T22S R4W S1 BT.</p> <p>A cedar, 11 ins. diam., bears S. 80° W., $58\frac{1}{2}$ lks. dist., mkd. T22S R4W S2 BT.</p> <p>A fir, 12 ins. diam., bears N. 27° W., 43 lks. dist., mkd. T21S R4W S35 BT.</p> <p>Reset Iron Pipe alongside the iron post.</p> <p>N. $0^{\circ} 15'$ E., between secs. 35 and 36, marking and blazing the true line.</p> <p>Descend 34 ft. along E. slope, through scattering timber and light undergrowth.</p>	T 21 S	R 4 W	S 35	S 36	S 2	S 1	T 22 S		1958	
T 21 S	R 4 W										
S 35	S 36										
S 2	S 1										
T 22 S											
1958											
2.80	Branch, 5 lks. wide, course S. 20° E.; ascend 110 ft. over SW. slope changing to S. slope.										
6.53	Spur, slopes E.; descend 11 ft. along E. slope.										
10.52	Enter partially logged area, edge bears N. and E.										
12.52	Foot of descent, slopes E.; ascend 138 ft. over SE. slope changing to S. slope.										
20.05	<p>From this point a locally established S 1/16 cor. of secs. 35 & 36, bears West, 6 lks. dist., monumented with fir stake, 3 ins. square, protruding 3 ft. above ground, from which</p> <p style="margin-left: 40px;">A sawed cedar stump, 64 ins. diam., bears N. $62\frac{1}{2}^{\circ}$ E., 83 lks. dist., with no marks remaining on opened and rotted blaze.</p> <p style="margin-left: 40px;">A fir, 58 ins. diam., bears N. 52° W., 70 lks. dist., with scribe marks CS BT visible on opened blaze.</p> <p>Leave logged area, edge bears E. and S.; enter heavy timber and dense undergrowth.</p>										
25.09	Spur ridge, bears NW. and SE.; descend 9 ft. along E. slope.										