

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the E. Bdy., T. 23 S., R. 3 W.

CHAINS

T 23 S  
R 2 W  
1/4 S19  
1959

from which

A hemlock, 10 ins. diam., bears N.  $10\frac{1}{4}^\circ$  E.,  $12\frac{1}{2}$  lks. dist.,  
mkd.  $\frac{1}{4}$  S19 BT.

A hemlock, 9 ins. diam., bears S.  $43^\circ$  E., 6 lks. dist.,  
mkd.  $\frac{1}{4}$  S19 BT.

Descend 139 ft. over NE. slope.

14.69 Ravine, drains NE.; asc. 22 ft. over SE. slope.

18.90 Top of ascent, slopes E.; desc. 17 ft. over NE. slope.

20.87 Creek, 1 lk. wide, course SE.; asc. 223 ft. over SE. slope.

29.47 Top of ascent, slopes E.; desc. 182 ft. over NE. slope.

40.50 Point for the cor. of secs. 13 and 24 only, at proportionate  
distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 26 ins. in the  
ground, with brass cap mkd.

T 23 S |  
R 3 W | T 23 S  
S 13 | R 2 W  
S 24 | S 19  
1959

from which

A fir, 15 ins. diam., bears S.  $24\frac{1}{2}^\circ$  W., 12 lks. dist.,  
mkd. T23S R3W S24 BT.

A fir, 12 ins. diam., bears N.  $34\frac{1}{2}^\circ$  W., 44 lks. dist.,  
mkd. T23S R3W S13 BT.

Land, mountainous.

Soil, clay and clay loam.

Timber, fir, hemlock, cedar, maple, alder, yew and dogwood;

Undergrowth, vine maple, hazel, fern, salal and Oregon grape.

N.  $0^\circ 42'$  E., along the E. bdy. of sec. 13.

Descend 124 ft. over NE. slope, through heavy timber and  
scattered undergrowth.

8.605 Point for Chandler's closing cor. of secs. 18 and 19, W. bdy.  
T. 23 S., R. 2 W., at proportionate distance; there is no  
remaining evidence of the original corner. This now becomes a  
corner of minimum control for secs. 18 and 19 only.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 26 ins. in the  
ground, with brass cap mkd.

T 23 S | T 23 S  
R 3 W | R 2 W  
S 13 | S 18  
S 13 | S 19  
1959

from which

+++++