

# County Surveyor's Record, Douglas County, Oregon

Retracement of South Boundary of T. 29 S., R. 9 W.

CHAINS

June 20th. - At this corner I set off 23° 27' N. on the decl. arc. and at 12h. 1m. l.m.t., and observe the sun on the meridian. The resultant lat. is 43° 1'.

Thence I run

West on blank line along S. bdy. of sec. 31.

2.10 A creek 6 lks. wide; course S. falls above line. Steep ascent about 200 ft. in dense undergrowth.

40.59 Intersect point for  $\frac{1}{4}$  sec. cor. Post and one witness tree gone. Set a Cedar Post 3 ft. long 4 ins. sq., 24 ins. in ground, for  $\frac{1}{4}$  sec. cor. in lieu of decayed stake marked:  $\frac{1}{4}$  S 31 on N., and 6 on S., faces from which: Old Wits.; A Fir, 48 ins. in diam., bears N. 45° E., 66 lks. dist. marked:  $\frac{1}{4}$  S31 B T.

New witness tree, a Cedar 50 ins. in diam., bears S. 25° W. 81 lks. dist., marked:  $\frac{1}{4}$  S 6 B T.

62.30 A creek 10 lks. wide; course S. in deep canyon. Steep ascent about 400 ft.

71.75 Top of mountain, course N, W, and S. E. Steep descent.

82.39 The established corner of Tps. 29 and 30 S., R. 9 W., which is a stone 32 x 32 x 18 ins. above ground, firmly set and marked with 6 notches on South and East faces from which:

A rock 5 ft. in diam. 4 ft. high, bears N. 68° E., 28 links dist., marked with an X.

A-Fir-30-ins.-diam.-bears-S.-83°-W.-230-lks.-dist.-mkd:  
T-30-S-R-10-W-S-1-B-T

A-Fir-30-ins.-in-diam.-bears-N.-89 $\frac{1}{2}$ °-W.-244-lks.-dist.-mkd:  
T-29-S-R-10-W-S-36-B-T

A rock 3 x 2 x 1 ft. above ground bears S. 70° E. 20 lks. marked X.

Notes of above cor. not fully agreeing with notes furnished by the Surveyor General, but nearly so.

Land, ountainous. Soil clay and stony, 3rd. rate. Timber, chiefly burned fir, cedar and hemlock. Undergrowth, fir, hemlock, cedar, alder, maple, salal, huckleberry and thimbleberry. Mountainous land, or land heavily timbered or covered with dense undergrowth and exceptionally difficult to survey --82.39 chs. June 20th, 1907

June 21st - Upon investigation, I find there are two corners set for the S. W. Cor. of Twp. 29 S., R. 9 W., viz: One set by Dennis Hathorn under contract No. 57, and the other by Wm. P. Wright under contract No. 358. The latter corner bears N. 45° W. 2.83 chs. dist. from the corner set by Deputy Hathorn. Both corners are standing and agree with the notes of each as furnished by the Surveyor General.

Having no special instructions in this matter, I go to the corner established by Deputy Wright and run South 2.00 chs. at which point I find it to be 2.08 chs. West of the corner established by Hathorn; at this point I set a cedar post 3 ft. long, 4 ins. sq., 24 ins. in the ground for a closing corner of T. 29 S., R. 9 W. marked: C C T 29 S and 6 grooves on the N., and R 9 W S 31, and 6 grooves on the E. from which:

Voted in Margin  
 See page 1 of notes here attached for this corner

See page 1 of notes here attached for this corner destroyed.