

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the W. Bdy. of T. 19 S., R. 8 W.

CHAINS

T 19 S	
$\frac{1}{4}$ S 24	
R 9 W	
1957	

from which

A fir, 72 ins. diam., bears N. 40° W., 26 lks. dist., mkd.  $\frac{1}{4}$  S24 BT.

A hemlock, 14 ins. diam., bears S. 33° W., 95 lks. dist., mkd.  $\frac{1}{4}$  S24 BT.

Ascend 10 ft. over  $\overline{SW}$  slope.

78.40 Top of ascent, slopes W.; desc. 12 ft. over NW. slope.

79.80 The corner of secs. 18 and 19 only, determined at record distance from each of the original bearing trees:

A cedar, 29 ins. diam., bears N. 60° E., 32 lks. dist., with a healed blaze facing the corner. (Record bearing, N. 30° E.)

A cedar, 26 ins. diam., bears S. 53 $\frac{1}{2}$ ° E., 29 lks. dist., with scribe marks T19S R8W S19 BT visible on unhealed blaze facing the corner. (Record bearing, S.70°E.)

Find no trace of original 6 inch diam. fir corner tree.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T 19 S		T 19 S
S 24		S 18
R 9 W		S 19
		R 8 W
		1957

Land, mountainous.

Soil, Sandy clay loam.

Timber, fir, hemlock, cedar, alder, maple, madrona, and yew.

Undergrowth, salmonberry, vine maple, thimbleberry, arrowwood, red huckleberry, evergreen huckleberry and ceanothus.

N. 0° 51' W., along the W. bdy. of sec. 18.

Descend 25 ft. over NW. slope, through heavy timber and dense undergrowth.

0.12 Unrecorded original line tree; a fir, 75 ins. diam., with 2 notches each on N. and S. sides.

2.90 Branch, 6 lks. wide, course S. 15° W.; asc. 35 ft. over SE. slope, changing to E. slope.

9.65 Spring branch, 1 lk. wide, course S. 75° E.; asc. 65 ft. over E. slope.

12.55 Spur, slopes E.; desc. 30 ft. over NE. slope.

15.45 Spring branch, 2 lks. wide, course S. 80° E.; asc. 125 ft. over SE. slope.

18.395 Point for the N 1/16 sec. cor. of sec. 24 only, on the E. bdy. of T. 19 S., R. 9 W.

FD. O.K. by:  
L. ROBERTS  
MARCH, 1982  
SEE M 91-73