

13604
 County Surveyor's Record, Douglas County, Oregon

-19-

Dependent Resurvey of a Portion of the E. Bdy. of T. 19 S., R. 10 W.

CHAINS

T 19 S | T 19 S
 S 13 | S 18
 S 19 | S 19 CC
 R 10 W | R 9 W
 1958

from which

A fir, 58 ins. diam., bears N. 82° E., 63 lks. dist.,
 mkd. T19S R9W S18 CC BT.

A fir, 43 ins. diam., bears S. 6° E., 62 lks. dist.,
 mkd. T19S R9W S19 CC BT.

Descend 117 ft. over NE. slope.

26.60 Dry branch, 3 lks. wide, course E.; asc. 96 ft. over SE. slope.

30.75 Spur, slopes N. 80° E.; desc. 42 ft. over NE. slope.

33.45 Dry branch, 3 lks. wide, course E.; asc. 135 ft. over SE. slope.

42.95 Spur, slopes S. 80° E.; desc. 70 ft. over NE. slope.

46.10 Branch, 3 lks. wide, course S. 40° E.; asc. 10 ft. over SE. slope.

46.48 Point for the $\frac{1}{4}$ sec. cor. of sec. 13 only, at proportionate distance;
 there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground,
 with brass cap mkd.

$\frac{1}{4}$
 T 19 S |
 S 13 |
 R 10 W |
 1958

from which

A cedar, 33 ins. diam., bears N. 80 $\frac{1}{4}$ ° W., 67 lks. dist.,
 mkd. $\frac{1}{4}$ S13 BT.

A fir, 48 ins. diam., bears S. 70° W., 40 lks. dist.,
 mkd. $\frac{1}{4}$ S13 BT.

Ascend 86 ft. over SE. slope.

54.45 Ravine, course SE.; asc. 188 ft. over SE. slope.

56.38 Point for the $\frac{1}{4}$ sec. cor. of sec. 18 only, on the W. bdy. of
 T 19 S., R. 9 W., at midpoint between closing corners.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground,
 with brass cap mkd.

Find OK
 6-21 R. Ward
 M 113-37 A48

$\frac{1}{4}$
 T 19 S
 S 18
 R 9 W
 1958

from which

A fir, 38 ins. diam., bears N. 70° E., 9 $\frac{1}{2}$ lks. dist.,
 mkd. $\frac{1}{4}$ S18 BT.

A fir, 41 ins. diam., bears S. 60° E., 43 lks. dist.,
 mkd. $\frac{1}{4}$ S18 BT.