

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of Subdivisional Lines of T. 19 S., R. 9 W.

CHAINS

distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

1/4 S 25 / S 36
T 19 S R 9 W
1958

from which

An alder, 22 ins. diam., bears N. 50 3/4° W., 79 lks. dist., mkd. 1/4 S25 BT.

A maple, 20 ins. diam., bears S. 67° E., 16 lks. dist., mkd. 1/4 S36 BT.

Ascend 30 ft. over NW. slope.

41.70 Spur, slopes N.; desc. 85 ft. over E. slope.

47.10 Ravine, course N.; asc. 260 ft. over W. slope.

50.40 Spur, slopes N. 20° E.; desc. 70 ft. over SE. slope.

59.55 Point for the E 1/16 Sec. Cor. of secs. 25 and 36.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

E 1/16 S 25 / S 36
1958

from which

A hemlock, 10 ins. diam., bears N. 22° W., 42 lks. dist., mkd. E 1/16 S25 BT.

A fir, 32 ins. diam., bears S. 8° E., 39 lks. dist., mkd. E 1/16 S36 BT.

Descend 60 ft. over SE. slope.

69.20 Spur, slopes SE.; desc. 100 ft. over NE. slope.

73.90 Spur, slopes N.; desc. 240 ft. over SE. slope.

79.40 Point for the 1/16 80 sec. cor. of secs. 25 and 36.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

1/16 S 25 / S 36 80
1958

from which

A cedar, 55 ins. diam., bears N. 61 3/4° W., 40 lks. dist., mkd. 1/16 S25 80 BT.

A hemlock, 22 ins. diam., bears S. 23° W., 73 lks. dist., mkd. 1/16 S36 80 BT.

Descend 55 ft. over NE. slope.

83.20 Creek, 9 lks. wide, course SE.; asc. 85 ft. over broken S. slope.

88.50 Ravine, course S. 40° W.; asc. 140 ft. over SW. slope.