

County Surveyor's Record, Douglas County, Oregon

-34-

Dependent Resurvey of Portion of Subdivisional Lines of T. 19 S., R. 9 W.

CHAINS					
	<p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <table style="margin: auto;"> <tr><td>T 19 S R 9 W</td></tr> <tr><td>S 27 S 26</td></tr> <tr><td>S 34 S 35</td></tr> <tr><td>1957</td></tr> </table> </div> <p>from which new bearing trees:</p> <p style="padding-left: 40px;">An alder, 22 ins. diam., bears N. 49° E., 27 lks. dist., mkd. T19S R9W S26 BT.</p> <p style="padding-left: 40px;">A cedar, 50 ins. diam., bears S. 19½° W., 123 lks. dist., mkd. T19S R9W S27 BT.</p> <p>Land, mountainous. Soil, sandy clay loam. Timber, fir, hemlock, cedar, maple, alder, chinquapin, dogwood, cascara, madrona, and yew. Undergrowth, vine maple, salmonberry, hazel, arrowwood, red huckleberry, evergreen huckleberry, and sword fern.</p>	T 19 S R 9 W	S 27 S 26	S 34 S 35	1957
T 19 S R 9 W					
S 27 S 26					
S 34 S 35					
1957					
	<p>From the cor. of secs. 25, 26, 35 and 36.</p> <p>S. 86° 20' W., bet. secs. 26 and 35.</p> <p>Descend 210 ft. over broken SW. slope, through heavy timber and dense undergrowth.</p>				
6.95	Gold Creek, 20 lks. wide, course S. 20° E.; asc. 160 ft. over broken NE. slope.				
23.25	Ravine, course NE.; asc. 260 ft. over NE. slope.				
31.05	Spur, slopes N. 20° E.; desc. 100 ft. along broken N. Slope.				
38.65	Ravine, course N.; asc. 30 ft. over NE. slope.				
39.725	<p>Point for the ¼ sec. cor. of secs. 26 and 35, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <table style="margin: auto;"> <tr><td>¼ S 26</td></tr> <tr><td>¼ S 35</td></tr> <tr><td>T.19 S R 9 W</td></tr> <tr><td>1958</td></tr> </table> </div> <p>from which</p> <p style="padding-left: 40px;">A fir, 16 ins. diam., bears N. 36° E., 50 lks. dist., mkd. ¼ S26 BT.</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears S. 33° E., 82 lks. dist., mkd. ¼ S35 BT.</p> <p>Ascend 210 ft. over broken NE. slope.</p>	¼ S 26	¼ S 35	T.19 S R 9 W	1958
¼ S 26					
¼ S 35					
T.19 S R 9 W					
1958					
43.45	Ridge, divide between Gold Creek and Beaver Creek bears N. 60° W. and S. 60° E.; desc. 490 ft. over broken W. slope.				
55.25	Ravine, course S. 80° W.; asc. 180 ft. along broken S. slope.				
63.45	Spur, slopes SW.; desc. 370 ft. over broken NW. slope.				