

Dependent Resurvey of a portion of the E. Bdy., T. 21 S., R. 6 W.

CHAINS

2.00 Wooden fence, bears E. and W.; asc. 102 ft., through logged area.

20.10 Point for the N 1/16 sec. cor. of secs. 1 and 6.

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

| |
|---------|
| N 1/16 |
| SI S6 |
| 1962 |

from which

A fir, 8 ins. diam., bears S. 19° E., 162 lks. dist., mkd.
N 1/16 S6 BT.A fir, 8 ins. diam., bears S. 66° W., 220 lks. dist., mkd.
N 1/16 S1 BT.

Ascend slightly over S. slope, through logged area and scattering fir reproduction.

20.80 Dirt road, 12 lks. wide, bears N. 45° E. and S. 45° W.

29.20 Enter heavy timber, edge bears E. and W.; asc. 93 ft. over SE slope

35.40 Dirt road, 15 lks. wide, bears N. 70° E. and S. 70° W.; asc. 15 ft. over SE. slope.

38.00 Spur slopes S.; desc. 8 ft. over NE. slope.

40.20 The cor. of Tps. 20 and 21 S., Rs. 5 and 6 W., which has been perpetuated with a Douglas County survey marker, an iron post, 1 in. diam., protruding 8 ins. from the ground, firmly set, with brass cap mkd.

| |
|---------------|
| 1958 |
| T20S |
| R S36 S31 R |
| 6 5 |
| W S 1 S 6 W |
| T21S |

from which the remaining original bearing trees:

A cedar, 52 ins. diam., bears N. 36° E., 105 lks. dist., with a healed blaze.

A sawed fir stump, 48 ins. diam., bears S. 82° W., 89 lks. dist., with bottom of healed blaze visible.

A sawed fir stump, 48 ins. diam., bears N. 87° W., 120 lks. dist., mkd. S on opened blaze.

trees mkd. by County Surveyor:

A fir, 14 ins. diam., bears N. 45° E., 49 lks. dist., mkd.
S31 T20S R5W CS BT.A fir, 14 ins. diam., bears S. 78° E., 48 lks. dist., mkd.
S6 T21S R5W CS BT.A cedar, 20 ins. diam., bears S. 75° W., 147 lks. dist., mkd.
S1 T21S R6W CS BT.A madrone, 24 ins. diam., bears N. 18° W., 159 lks. dist., mkd.
S36 T20S R6W CS BT.

and new bearing trees: