

County Surveyor's Record, Douglas County, Oregon  
-10-

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 22 S., R. 8 W.

|   |   |
|---|---|
| <p>CHAINS<br/>18.95<br/>20.00<br/>23.00<br/>24.55<br/>26.80<br/>38.00<br/>39.80<br/>40.30</p> | <p>Top of ascent, slopes S.; desc. 16 ft. along S. slope.</p> <p>Enter timber; edge bears N. and S.</p> <p>Woven wire fence, bears N. and S.</p> <p>Spur, slopes S. 20° E.; desc. 326 ft. over SW. slope.</p> <p>Same dirt road, 15 lks. wide, bears N. 35° W. and S. 35° E.</p> <p>Dirt road, 15 lks. wide, bears N. 20° W. and S. 20° E.</p> <p>Creek, 10 lks. wide, course N. 10° W.; asc. 16 ft. over E. slope.</p> <p>The <math>\frac{1}{4}</math> Sec. cor. of secs. 28 and 33, determined at record bearing &amp; distance from the only remaining original bearing Tree:</p> <p style="padding-left: 40px;">A fir, 67 ins. diam., bears N. 45° W., 9 lks. dist., with fragmentary scribe marks visible on bark blaze.</p> <p style="padding-left: 40px;">Set an iron post, 28 ins. long, 2<math>\frac{1}{2}</math> ins. diam., 26 ins. in the ground, with brass cap marked</p> <div style="text-align: center; padding-left: 100px;"> <math display="block">\frac{1}{4} \begin{array}{l} S 28 \\ S 33 \end{array}</math> <p>T 22 S R 8 W<br/>1962</p> </div> <p>from which new bearing trees</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears N. 55<math>\frac{1}{4}</math>° W., 26<math>\frac{1}{2}</math> lks. dist., marked <math>\frac{1}{4}</math> S28 BT.</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S. 7<math>\frac{1}{2}</math>° W., 21 lks. dist., marked <math>\frac{1}{4}</math> S33 BT.</p> <hr style="width: 20%; margin: 20px auto;"/> <p>N. 89° 44' W., beginning new measurement.</p> <p>Ascend 566 ft. over general E. slope, through second-growth timber and dense undergrowth.</p> <p>25.65 Leave timber, enter logged area, edge bears NW. and SW.</p> <p>30.00 Ridge, bears N. 50° E. and S. 50° W.; asc. 53 ft. over NE. slope.</p> <p>36.35 Spur, slopes N. 30° W.; desc. 107 ft. over SW. slope.</p> <p>39.58 The cor. of secs. 28, 29, 32 and 33.</p> <p>Land, mountainous.<br/>Soil, sandy clay loam.<br/>Timber, fir, hemlock, cedar, maple, alder, myrtle, madrone, dogwood, oak, and chinquapin; undergrowth, vine maple, hazel, arrowwood, huckleberry, salmonberry, poison oak and fern.</p> |
|---|---|

GENERAL DESCRIPTION

The land embraced in the notes of the foregoing survey is located in the coastal mountains on the south side of the Umpqua River, about four miles southwesterly from Elkton, Oregon. The area is drained by the Umpqua River and a number of small tributaries. The elevation ranges from about 240 feet above sea level near the  $\frac{1}{4}$  section corner of sections 28 and 33 to about 960 feet above sea level on the ridge 9 chains east of the corner of sections 32 and 33 on the south boundary of the township.

Access is by way of privately owned graveled and dirt roads extending into section 33 from northwesterly and southeasterly directions. These roads connect with county roads along the left bank of the Umpqua River.