

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the W. Bdy., T. 24 S., R. 6 W.

CHAINS	
	<p>A fir, 8 ins. diam., bears N. 5° W., 40½ lks. dist., mkd. T24S R7W S24 CC BT.</p> <p>Descend 430 ft. over N. slope.</p>
20.12	<p>Point for the S 1/16 sec. cor. of sec. 19 only.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 28 ins. in the ground with brass cap mkd.</p> <p style="text-align: right;">See BLM rehabilitation of this corner Added 1 new BT (2003) Vol. 54 Page 21119</p> <p style="text-align: center;">S 1/16 S 19 1962</p> <p>from which</p> <p>A cedar, 10 ins. diam., bears N. 24° E., 207 lks. dist., mkd. S 1/16 S19 BT.</p> <p>A fir, 18 ins. diam., bears S. 74° E., 87 lks. dist., mkd. S 1/16 S19 BT.</p> <p>Descend 245 ft. along W. slope, changing to NW. slope.</p>
36.60	Creek, 3 lks. wide, course N. 60° W.; asc. 80 ft. over SW. slope.
38.15	Spur, slopes N. 55° W.; desc. 40 ft. over NE. slope.
39.35	Creek, 1 lk. wide, course N. 55° W.; asc. 30 ft. over SW. slope.
40.24	<p>The ¼ sec. cor. of sec. 19 only, as determined from the one remaining original bearing tree:</p> <p>A fir, 30 ins. diam., bears S. 58½° E., 72 lks. dist., mkd. ¼ S BT.</p> <p>At the corner point</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 28 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 24 S R 6 W ¼ S19 1962</p> <p>from which</p> <p>A white fir, 10 ins. diam., bears N. 34° E., 124 lks. dist., mkd. ¼ S19 BT.</p> <p>A white fir, 8 ins. diam., bears S. 69° E., 151 lks. dist., mkd. ¼ S19 BT.</p> <hr/> <p>N. 0° 26' E., beginning new measurement.</p> <p>Ascend 115 ft. over SW. slope.</p>
7.50	Spur, slopes N. 80° W.; desc. 80 ft. over NE. slope.
10.90	Draw, drains N. 60° W.; asc. 20 ft. along W. slope.
12.30	Low spur, slopes W.; desc. 60 ft. along W. slope.
17.60	Draw, drains N. 70° W.; asc. 20 ft. along W. slope.
19.65	Spur, slopes N. 70° W.; desc. 15 ft. over N. slope.