

County Surveyor's Record, ⁵Douglas County, Oregon

Dependent Resurvey of a Portion of the W. bdy., T. 24 S., R. 6 W.

CHAINS

A white oak, 7 ins. diam., bears N. 49° W., 107 lks. dist.,
mkd. T24S R7W S13 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar; undergrowth, ceanothus, salal, hazel,
fir reproduction, vine maple and poison oak.

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 24 S., R. 6 W.

(Restoring the 1891 Survey by Williams R. Whipple.)

From the cor. of secs. 19, 20, 29 and 30, perpetuated by a ford
axle/gear, 36 ins. long, 1 in. diam., firmly set 22 ins. in the
ground. F. C. Frear, County Roadmaster, rehabilitated this cor.
from two original bearing trees, of which none remain, in 1932,
and marked new bearing trees:

A white oak, 21 ins. diam., bears N. 14° E., 39 lks. dist.,
with a healed blaze.

A white oak, 18 ins. diam., bears S. 15° E., 32 lks. dist.,
with a rotted face.

A white oak, 12 ins. diam., bears S. 38° W., 33 lks. dist.,
with a healed blaze.

A white oak, 16 ins. diam., bears N. 67° W., 30 lks. dist.,
with a rotted face.

and trees marked by the County Surveyor

A white oak, 12 ins. diam., bears S. 77° E., 10 lks. dist.,
mkd. S29T24S R6W CS BT.

A white oak, 14 ins. diam., bears N. 45° W., 66 lks. dist.,
mkd. S19 T24S R6W CS BT.

At the corner point.

Set an iron post, 30 ins. long, 2½ ins. diam., 26 ins. in the
ground, with brass cap mkd.

T 24 S R 6 W
S 19 S 20
S 30 S 29
1962

from which

A white oak, 21 ins. diam., bears N. 14° E., 39 lks. dist.,
mkd. T24S R6W S20 BT.

A white oak, 25 ins. diam., bears S. 24° E., 37 lks. dist.,
mkd. T24S R6W S29 BT.

A fir, 13 ins. diam., bears S. 75½° W., 78 lks. dist., mkd.
T24S R6W S30 BT.

A fir, 12 ins. diam., bears N. 40° W., 99 lks. dist., mkd.
T24S R6W S19 BT.

Insert axle/gear inside iron post.

N. 89° 38' W., bet. sec. 19 and 30, marking and blazing true line.

Descend 10 ft. over SW. slope, through scattering timber and
light undergrowth.