

## County Surveyor's Record, Douglas County, Oregon

-9-

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 24 S., R. 6 W.

## CHAINS

and trees marked by the County Surveyor

A madrone, 4 ins. diam., bears N. 51° E., 69 lks. dist.,  
mkd. S17 CS BT.

A madrone, 5 ins. diam., bears S. 17½° E., 100 lks. dist.,  
mkd. S20 CS BT.

A madrone, 4 ins. diam., bears N. 18° W., 54 lks. dist.,  
mkd. S18 CS BT.

and new bearing trees

A madrone, 6 ins. diam., bears N. 26° E., 138 lks. dist.,  
mkd. T24S R6W S17 BT.

A madrone, 6 ins. diam., bears S. 54° E., 57 lks. dist.,  
mkd. T24S R6W S20 BT.

A madrone, 6 ins. diam., bears S. 45° W., 78 lks. dist.,  
mkd. T24S R6W S19 BT.

A madrone, 6 ins. diam., bears N. 60° W., 148 lks. dist.,  
mkd. T24S R6W S18 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock and cedar; undergrowth, salal, ceanothus,  
madrone, reproduction and poison oak.

N. 89° 30' W., bet. sec. 18 and 19.

Descend 200 ft. over W. slope, changing to NW. slope, across logged  
and burned area.

1.80 Dirt road, 25 lks. wide, bears N. 55° E. and S. 55° W.

11.00 Creek, 2 lks. wide, course S. 25° W.; asc. 200 ft. over steep  
SE slope.

23.80 Broad spur, slopes S.; desc. 60 ft. over SW. slope.

27.55 Ravine, drains S.; asc. 35 ft. over SE. slope.

30.55 Spur, ridge, bears N. 45° E. and S. 45° W.; wire fence, bears  
same; desc. 165 ft. over W. slope.39.97 The ¼ sec. cor. of secs. 18 and 19, perpetuated by a Douglas County  
survey mark, an iron post, 1½ ins. diam., firmly set, with brass  
cap mkd.

COUNTY SURVEYOR'S OFFICE

$$\frac{1}{4} \frac{S18}{S19}$$

T 24 S R 6 W  
1959

from which the remains of the original bearing trees

A fir, dead and down, 72 ins. diam., bears N. 6° E.,  
163 lks. dist., with a rotted face.

A black oak, 56 ins. diam., bears S. 18° 50' E., 187 lks.  
dist., mkd. ¼ S.

and trees marked by the County Surveyor