

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 19, T. 24 S. R. 6 W.

CHAINS	Land, mountainous. Soil, rocky clay. Timber, fir, hemlock and cedar; undergrowth, salal, ceanothus, vine maple, cattail, blackberry and poison oak.
	From the E 1/16 sec. cor. of secs. 19 and 30. N. 0° 10' E., along the N. and S. center line of the SE $\frac{1}{4}$ of sec. 19. Ascend 255 ft. over SW. slope.
1.50	Road, hard-surfaced, 50 lks. wide, bears S. 60° E. and N. 60° W.
6.65	Transmission line, 2 strand, bears N. 65° W. and S. 65° E.
13.55	Spur, slopes W.; asc. 25 ft. along W. slope.
20.17	Point for the SE 1/16 sec. cor. of sec. 19, at the intersection with the E. and W. center line of the SE $\frac{1}{4}$. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 28 ins. in the ground, with brass cap mkd. SE 1/16 S 19 1962 from which A fir, 20 ins. diam., bears S. 64° E., 85 lks. dist., mkd. SE 1/16 S19 BT. A fir, 8 ins. diam., bears S. 45 $\frac{1}{2}$ ° W., 39 lks. dist., mkd. SE 1/16 S19 BT. Ascend 25 ft. along W. slope, changing to SW. slope.
22.50	Spur ridge, bears N. 60° W. and S. 60° E.; desc. 125 ft. over NE. slope.
30.30	Gully, drains N. 35° W.; asc. 20 ft. over SW. slope.
35.00	Spur, slopes N. 30° W.; desc. 90 ft. over NE. slope.
40.32	The center E 1/16 sec. cor. of sec. 19.
	From the S 1/16 sec. cor. of secs. 19 and 20. N. 89° 50' W.; along the E. and W. center line of the SE $\frac{1}{4}$ of sec. 19. Descend 100 ft. along N. slope.
13.60	Spur ridge, bears NW. and SE.; desc. 140 ft. over SW. slope, changing to W. slope.
19.88	The SE 1/16 sec. cor. of sec. 19. Descend 430 ft. over SW. slope, changing to W. slope.
31.75	Dirt road, 15 lks. wide, bears N. 10° W. and S. 10° E.
32.80	Transmission line, 2 strand, bears N. 30° W. and S. 30° E.
34.45	Road, hard-surfaced, 50 lks. wide, bears N. 10° W. and S. 10° E.