

County Surveyor's Record, Douglas County, Oregon

-17-

Subdivision of Section 19, T. 24 S., R. 6 W.

CHAINS

- From the center N 1/16 sec. cor. of sec. 19.
- West, along the E. and W. center line of the NW $\frac{1}{4}$.
- Descend 105 ft. over rocky SW. slope.
- 3.75 Gully, drains S. 40° W.; asc. 15 ft. over SE. slope.
- 6.75 Spur, slopes SW.; desc. 250 ft. over SW. slope, changing to W. slope.
- 15.80 Transmission line, 2 strand, bears S. 25° E. and N. 25° W.
- 19.60 Dirt road, 15 lks. wide, bears N. and S.
- 20.14 The NW 1/16 sec. cor. of sec. 19.
- Descend 60 ft. over W. slope.
- 23.00 Creek, 1 lk. wide, course SW.; desc. 85 ft. over SW. slope.
- 25.80 Road, hard-surfaced, 50 lks. wide, bears S. 50° E. and N. 50° W.
- 27.90 Little Canyon Creek, 30 lks. wide, course N. 65° W.; asc. 280 ft. over steep NE. slope.
- 36.85 Spur, slopes N. 15° E.; asc. 45 ft. along N. slope.
- 39.00 Spur, slopes N.; desc. 20 ft. along N. slope.
- 42.18 The N 1/16 sec. cor. of sec. 19 only, on the W. bdy of the Twp.

GENERAL DESCRIPTION

The portion of township 24 south, range 6 west that was re-surveyed lies about 8 miles northwest of Sutherlin, Oregon. Section 19 consists of high, sharp ridges and long broad slopes. Only a small portion is used for agricultural purposes. The soil is a rocky clay, depth varying from several feet on the lower slopes to exposed bedrock on the higher elevations. The low point in section 19 is on the west boundary, where Little Canyon Creek crosses at an elevation of about 300 feet above sea level. The highest point was crossed on a spur of Spooner Ridge, on the north boundary with an elevation in excess of 1,200 feet above sea level. Most of the section has been left to logging and timber, with a few acres near the center $\frac{1}{4}$ section corner and in bottom land cultivated for vegetable crops. Grazing to a limited extent is carried out on the high ridges, where a few natural prairies exist.

The timber is predominately Douglas Fir, with lesser volumes of hemlock, cedar and white fir. Scattered throughout the section can be found myrtle, white and black oak, madrone, willow, yew, alder, maple and chinquapin. Undergrowth consists of salal, ceanothus, vine maple, poison oak, Oregon grape, blackberry, hazel, fern and salmonberry.

Little Canyon Creek, with its small tributaries, drains the entire section. The flow is in a northwesterly direction. There is excellent access to section 19 via State Highway 225, which traverses the section in a northwesterly direction, along Little Canyon Creek. There are many infrequently used dirt roads connecting to State Highway No. 225, and all parts of the section can be reached by four-wheel drive vehicles.

In the vicinity of the center $\frac{1}{4}$ section corner of section 19, stands a vacant house and a cow shed. A still was located, recently used, in the cow shed. Another vacant house lies in the NW $\frac{1}{4}$ NW $\frac{1}{4}$ of