

County Surveyor's Record, Douglas County, Oregon

13137

#3

Remonumentation, Original Corner Points, T. 21 S., R. 9 W.

CHAINS

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked

T 21 S R 9 W
 $\frac{S 9 | S 10}{S 16 | S 15}$
 1963

from which new bearing trees

A fir, 14 ins. diam., bears N. 5° E., 17 lks. dist., marked T21S R9W S10 BT.

A fir, 8 ins. diam., bears S. $76\frac{1}{2}^\circ$ E., 20 lks. dist., marked T21S R9W S15 BT.

A fir, 18 ins. diam., bears S. $8\frac{1}{2}^\circ$ W., 20 lks. dist., marked T21S R9W S16 BT.

A fir, 8 ins. diam., bears N. 80° W., 7 lks. dist., marked T21S R9W S9 BT.

Deposit sandstone alongside iron post.

The $\frac{1}{4}$ sec. cor. secs. 10 and 15, determined at record bearing and distance from the original bearing trees:

A fir, 16 ins. diam., bears N. 25° W., 26 lks. dist., with fragmentary scribe marks visible on open blaze.

A fir, 32 ins. diam., bears S. 70° E., 28 lks. dist., with partially open blaze.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked

T21S R9W
 $\frac{\frac{1}{4} S 10}{S 15}$
 1963

from which a new bearing tree

A hemlock, 10 ins. diam., bears N. 20° W., 38 lks. dist., marked $\frac{1}{4}$ S10 BT.