

County Surveyor's Record, Douglas County, Oregon

3

CHAINS

Dependent Resurvey, Subdivisional Lines, T. 25 S., R. 5 W.

T. 25 S R 5 W

$$\begin{array}{c} \frac{1}{4} \\ \text{S } 9 \mid \text{S } 10 \\ 1962 \end{array}$$

from which

A fir, 14 ins. diam., bears N. 9° E., 139 lks. dist., marked $\frac{1}{4}$ S10 BT.

A fir, 16 ins. diam., bears S. 87° W., 59 lks. dist., marked $\frac{1}{4}$ S9 BT.

Descend 71 ft. over NE. slope.

- 43.10 Ravine, drains NW.; desc. 35 ft. along W. slope.
- 49.10 Bottom of descent, slopes W.; asc. 29 ft. over SW. slope.
- 53.75 Spur, slopes NW.; desc. 166 ft. over NW. slope.
- 60.00 Bottom of descent, slopes W.; asc. 40 ft. over SW. slope.
- 66.30 Spur, slopes SW.; desc. 25 ft. over NW. slope.
- 69.90 Ravine, drains SW.; asc. 230 ft. over SE. slope.
- 80.00 The cor. of secs. 3,4,9, and 10, perpetuated by the Douglas County Surveyor in 1960, monumented with an iron post, 1 in. diam., firmly set, projecting 15 ins. above the ground, with brass cap marked

County Surveyors Office

T 25 S R 5 W

$$\begin{array}{c} \text{S } 4 \mid \text{S } 3 \\ \text{S } 9 \mid \text{S } 10 \\ 1960 \end{array}$$

from which the original bearing trees

A white oak, 23 ins. diam., bears N. $45\frac{1}{2}^{\circ}$ E., 93 lks. dist., with axe marks visible on decayed blaze. (Record dist., 91 lks.)

A down and rotted madrone, 18 ins. diam., with no marks remaining on decayed blaze, lies on the ground near a stump hole which bears S. $49\frac{3}{4}^{\circ}$ E., 118 lks. dist.

A down and rotted white oak, 10 ins. diam., bears S. 34° W., 40 lks. dist., with fragmentary scribe marks visible on decayed blaze.

and the County Surveyors bearing trees

A white oak, 5 ins. diam., bears N. 79° E., 10 lks. dist., with scribe marks S3 CS BT visible on unhealed blaze.

A white oak, 7 ins. diam., bears S. 43° E., 27 lks. dist., with scribe marks T25S R5W S10 CS BT visible on unhealed blaze.

A white oak, 7 ins. diam., bears S. 54° W., 43 lks. dist., with scribe marks T25S R5W S9 CSBT