CHAINS	Dependent Resurvey, Subdivsional Lines, T. 25 S., R. 5 W.
	dist., with fragmentary scribe marks visible on partially healed blaze.
	Land, mountainous. Soil, clay loam. Timber, fir, cedar, madrone, oak, hemlock, and pine; undergrowth, poison oak, madrone, blackberry, thimbleberry, salal, and scotch broom.
	N. 0° 01' W., bet. secs. 8 and 9.
	Ascend 85 ft. over SE. slope, through scattering timber and light undergrowth.
6.20	Ridge, bears N. 60° E. and S. 60° W.; desc. 401 ft. over NW. slope.
16.30	Power line, 3 wires, bears N. 20° E. and S. 20° W.
19.96	Point for the S 1/16 sec. cor. of secs. 8 and 9.
	Se an iron post, 30 ins. long, 2½ ins. diam., 28 ins. in the ground, with brass cap marked S 1/16 S 8 | S 9 1962
	from which
	A white oak, 20 ins. diam., bears S. 86½° E., 46 lks. dist., marked S 1/16 S9 BT.
	A white oak, 10 ins. diam., bears N. 68° W., 67½ lks. dist., marked S 1/16 S8 BT.
	An iron rod, ½ in. diam., projecting 5 ins. above the ground, bears N. 55° E., 1½ lks. dist.
	An iron pipe, 1 in. diam., projecting 6 ins. above the ground, bears S. 78° W., 7½ lks. dist.
	Descend 47 ft. over NW. slope.
23.90	Ravine, drains NW.; asc. 42 ft. over SW. slope, leave timber, enter cleared field, edge bears NW. and SE.
33.90	Spur, slopes W.; desc. 29 ft. over NW. slope, leave field, enter scattering timber and light undergrowth, edge bears E. and W.
39.92	The ¼ sec. cor. of secs. 8 and 9, perpetuated by the County Surveyor in 1919 from the original bearing trees which are no longer in existance, andagain remonumented by the County Surveyor in 1960, with an iron post, 1 in. diam., firmly set, projecting 10 ins. above the ground, with brass cap marked FD. OK PER BENTZ Q-87 M 103-38 County Surveyors Office T 25 S | R 5 W S 8 | S 9 ¼ 1960
	fromwhich the County Surveyor's 1919 bearing trees
	A fir stump, 26 ins. diam., bears N. 26° W., 8 lks. dist., with no marks remaining on burned and rotted blaze.