

County Surveyor's Record, Douglas County, Oregon

11.

CHAINS	Subdivision of Section 9, T. 25 S., R. 5 W.
	<p>dist., marked CW 1/16 S9 BT.</p> <p>A fir, 15 ins. diam., bears S. $12\frac{1}{2}^{\circ}$ W., 68 lks. dist., marked CW 1/16 S9 BT.</p> <p>Ascend 18 ft. over NE. slope.</p>
61.10	Spur, slopes N.; desc. 164 ft. over broken NW. slope.
73.20	Dirt road, 15 lks. wide, bears N. 10° E. and S. 10° W.; also, power line, 3 wires, bears same as road.
79.94	The $\frac{1}{4}$ sec. cor. of secs. 8 and 9.
	<p>From the E 1/16 sec. cor. of secs. 9 and 16.</p> <p>N. 0° 03' E., on the N. and S. center line of the $SE\frac{1}{4}$ of sec. 9.</p> <p>Ascend 147 ft. over SE. slope, along W. edge of old logged area, through moderate undergrowth.</p>
20.00	Point for the SE 1/16 sec. cor. of sec. 9 at intersection with the E. and W. center of the $SE\frac{1}{4}$.
	<p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 28 ins. in the ground, with brass cap marked</p> <p style="text-align: center;">SE 1/16 S9 1962</p> <p>from which</p> <p>A fir, 13 ins. diam., bears S. 89° E., 60 lks. dist., marked SE 1/16 S9 BT.</p> <p>A fir, 13 ins. diam., bears S. 83° W., $27\frac{1}{2}$ lks. dist., marked SE 1/16 S9 BT.</p> <p>Enter timber, edge bears S. and E.</p> <p>Ascend 24 ft. over broken SE. slope.</p>
28.25	Ridge, bears N. 70° E. and S. 70° W.; desc. 239 ft. over broken NW. slope.
39.98	The center E 1/16 sec. cor. of sec. 9.
	<p>From the S 1/16 sec. cor. of secs. 9 and 10.</p> <p>N. 89° 28' W., on the E. and W. center line of the $SE\frac{1}{4}$ of sec. 9.</p> <p>Descend 200 ft. over W. slope, along the N. edge of old logged area, through moderate undergrowth.</p>
9.00	Ravine, drains S.; asc. 194 ft. over SE. slope.
19.97	The SE 1/16 sec. cor. of sec. 9.
	<p>Enter timber, edge bears S. and E.; ascend 51 ft. over SE. slope.</p>
24.50	Ridge, bears N. 10° E. and S.; desc. 122 ft. over W.